8147

Machinery.

ENGINEERING EDITION.

Index to Vol. XII.

September, 1905, to August, 1906.

1906.

THE INDUSTRIAL PRESS.
66 WEST BROADWAY,
NEW YORK.

Index to Vol. XII.

A.:
Index System 15
Milling Cutters 389
A. A.:
Acid to Dissolve High Speed Steel. (A. to H. & W. 57) . 46
The Proportions of Hand Taps 96
To Restore Burnt Steel.... 205
Cement for Cast Iron..... 205
Acid Test for Iron and Steel 205
Steel Welding Compound... 205
Packing for Gasoline Pumps. 268
Abbott, Paul W.:
Automatic Turret Work.... 421
Some Dogs and Drivers.... 658
Absorption Dynamometer, Fan as an 249
Accelerometer, An Electric.... 251
Accident in Steel Mill..... 193
Accurate Test and Inspection Gages for Small Duplicate Work, A Set of. J. V. Woodworth 73
Acetylene Gas Stored in Acetone 589
Acid Test for Iron and Steel. A. A. 205
Acid to Dissolve High Speed Steel. A. A. (A. to H. & W. 57) 46
Acker, W. H.:
Calculating Centrifugal Force 648
Adirondack Region, Power Development of the 405
Adjustable Die, An Angle Cut-off Die. J. L. Lucas..... 151
Advantages of Going Slow.... 640
Advertising, Mechanical. McAnic 150
Advertising, Tricks of..... 544
Air Brakes, Device for Testing. 95
Air Hoist for Casting Ladle. Lobdell 166
"Air Power" to be Discontinued 153
Alcohol and Its Effect on Industrial Conditions 567
Alcohol as a Fuel for Gas Engines 644
Alcohol as a Motor Fuel..... 567
Alcohol, "Denaturized"..... 195
Alcohol in the Arts..... 584
Alcohol used for Industrial Purposes 5
All-Around Man, Be an..... 490
Allis-Chalmers Shops, Floor-plate Work in the..... 627
Allis-Chalmers Steam Turbine. 236
Allis-Chalmers Turbine, Experiences with an 593
Alloy for Caliper and Gage Rod Castings. Jas. A. Pratt.... 424
Alloys for Drawing Colors on Steel. M. Dehne..... 323
Alloys Having Low. Fusing Temperature 6
Alloy Steels Hold Ten Times Their Own Weight..... 414
Alloy, What is An?..... 407
Almond, Thos. Richard..... 479
Aluminum Castings, Making (H. & W. 11)..... 324
Aluminum Solder. L. C. Carr. 661
Aluminum Solder 415
Aluminum Substituted for Tinfoil 26
Aluminum, To Solder. A. Eyles 606
American Woolen Co.'s New Mill 256
Amerika 194
Ammeter Used as a Speed Indicator 8
Ammonia Compressor with Small Clearance, An..... 239
Anderson, A.:
Proportions of Counterbores. 146
Angle Cut-off Die, An. J. L. Lucas 151
Angle Plates to Extend Shaper Table. R. A. Lachmann... 204
Angles of Screw Threads. T. E. Welsh 321
Angle without a Protractor, To Lay Out any. E. Werner.. 544
Angle, with Scale and Dividers, To Lay Off..... 250
Anneal High Speed Steel, To. I. W. Antano 153
Annealing Methods, Some. E. S. Wheeler 635
Anneal Steel or Iron, To. R. B. Casey 102
Antano, I. W.:
To Anneal High Speed Steel 153
To Harden a Hammer..... 267
To Line Up Lathe Centers.. 267
Anti-Freezing Solution. J. C... 323
Anti-Friction Metal. H. G. Kroeger 268
Anti-Leak, Bicycle Tire. M. E. Canek 661
Apprenticeship and Educational System of the General Electric Co., West Lynn, Mass.. 399
Apprenticeship Question, The. "Entropy" 629
Apprentices, Indentured..... 24
Area of Circles, for Small Diameters, To Use Tables of.. 364
Armature Bearings on Vertical Motors, Automatic Oiling Device for 145
Armatures, Tests for Faults in. N. G. Meade 478
Armatures, Winding of Direct Current 345
Armor Plate Situation, The... 641
Armor Plate, Testing Midvale Case-Hardened 19
Arras, C. C.:
Turret Knurling Tool..... 605
Artesian Wells, Device for Testing the Flow of..... 405
Artesian Well, Testing the Flow of an 187
Arthur, Jas.:
Elementary Dialing 509
Ash, Harry:
Hollow Grinding Center Reamer 45
To Imitate Case-Hardening.. 154
Ashley, Carroll:
Two Tool-holders and a Die Maker's Square 43
Graduating a Scale on a Planer 39
To Treat Inflamed Eyes, Care of the Eyes..... 154
To Solder Brass or Steel to Steel 204
To Make a Belt Pull..... 267
To Preserve Screws..... 322
A. S. M. E., Chattanooga Meeting of the 536
A. S. M. E., Meeting of the.. 170
A. S. M. E., New York Meeting of the 254
Aspenleiter, Jno.:
Repair of a Broken Bevel Gear 204
Atkinson, W. S.:
Pneumatic Babbitt Beating Machine 318
Attaching Cloth to Iron. J. A. Pratt 102
Attention to Caution 80
Auto Fire Engine with Liquid Fuel System, New Liverpool. F. C. Perkins 181
Automatic Machinery 46
Automatic Turret Work. P. W. Abbott 421
Automobile Contests 356
Automobile Contest, Two-Gallon 524
Automobile Line in Nevada Deserts 25
Automobile Operation, Cost of. 518
Automobile, Suggested Improvement in the 406
Automobile, The Future of the 408
Automobile Transmission Gear Teeth, Rounding 85
Automobile Turntable 95
Axe, The Works of an..... 358

B.:
Holding the work on a Horizontal Multiple Spindle Drill 262
Babbitt Beating Machine, Pneumatic. W. S. Atkinson 318
Babbitt from Exploding, To Prevent. H. K. Griggs.... 101
Babbitting, To Prepare a Shaft for. V. Smith 423
Bach, F. W.:
To Blacken Tin for Laying Out 490
Draftsman's Device for Drawing Letter Space Lines.. 541
Bachmann, H. J.:
The Advantage of Practical Shop Training for the Draftsman 41
To Harden Small Jig Bushings 153
Packing for Gas Engine Cylinders and Pipe Carrying Gasoline Vapor 154
Compound for Cleaning the Hands 154
Cement for Sticking Emery Paper on Small Grinder Disks 154
Drilling and Assembling Jig Milling Cutter for Clock Gears, etc..... 201
To Remove Broken Taps.. 267
Thread Cleaner for Chucks and Faceplates 267
To Remove Burnt Oil from Hardened Steel 268
Lubricant for High Speed Bearings 268
To Temper Twist Drill to Drill Hardened Steel.... 322
Hardening Without Cracking 542
Some Progress in Simple Press Work 569
Backing-Off Spring and Button Dies. J. S. Scott..... 543
Balancing Gas Engines, Method of 406
Baldwin Locomotive Works' Enormous Production of Locomotives 93
Ball Bearings, A New Use for. 37
Ball Bearings in Transmission Machinery of Automobiles, Extensive Use of 401
Ball Engine Co., The New Shop of the..... 351
Ball, M. H.:
Curved Side Countersink in Mandrel for Taper Lathe Work 101
Spring Fastener for Lathe Pointer 153
Band Saw for Armor Plate... 527
Band Saw Sharpening Device, Novel 94
Bank Window Grating, Fastening for 415
"Barney":
A Double-Ended Bevel..... 372
Beam Compass Converted into a Hatchet Planimeter. E. J. Lees 264
Beam Formulas. S. A. Moss. 32
Becker, O. M.:
Factory Education 163
An Experiment in Industrial Education 225
Beardsley, E. W.:
Instruction for Draftsmen.. 11
Kinks for Draftsmen..... 38
Bearings Held at the December Meeting of the A. S. M. E., The Discussion on 300
Bell Industry, The. S. E. Emmons 515
Bells, Something About the Manufacture of 532
Belt Cement, A. J. H. V.... 606
Belt Dressing. O. E. Perrigo. 424
Belt Elasticity, Loss of Velocity Ratio Due to..... 250
Belting at the Schieren Factory, The Manufacture of..... 464
Belt Preparations, Tests of.... 364
Belt Pull, To Make a. Carroll Ashley 267
Belts, Cement for. J. M. Menegus 606
Belt Shifter, A Handy. C. J. S. 149
Belt Shifter, German. Robt. Grimshaw 538
Belts, Horse Power Transmitted by. F. Wackermann. 559
Benjamin, C. H.:
The Friction of Roller Bearings 62
Bursting Strength of Cast Iron Cylinders..... 120
Laboratory Training 291
Sections of Cast Iron Beams 437
Bentley, T. S.:
The Packing of Machine Tools for Shipment..... 118
Bessemer:
Improvised Slip Gear..... 598
Bessemer Steel Lap-Welded Tubes, Collapsing Pressures of 506
Better Surroundings in the Foundry. A Plea for..... 79
Bevel, A Double-ended. "Barney" 372
Bevel Gear Chart. George J. Porter 18
Bevel Gear, Repair of a Broken. Jno. Aspenleiter 204
Bevel Gears Having Their Axes at Other than Right Angles, To Calculate the Center Angles of a Pair of. A. L. Westcott 539
Bicycle Tire Anti-Leak. M. E. Canek 661
Bicycle Tire Anti-Leak. F. Emerson 204
Bierbach, A. F.:
Chucking Pieces for Planer Work 322
Billet and Bar Passes, The Design of. B. H. Reddy..... 451
Blacken Tin for Laying Out, To. F. W. Bach..... 490
Blacken Zinc for Laying Out, To. R. M. 323
Black Varnish for Iron. O. G. 490
Blake, C. F.—Technical Reading and Formulas:
1 69
2 125
3 178
Brakes I. 619
Blank for a Cup, Finding the Size of. O. Eckelt..... 320
Blanking Die, Making a. C. F. Emerson 516
Blanking Dies from Excessive Warping in Hardening, To Prevent. C. F. Emerson.. 204
Blanking Punch and Die, Making a. H. R. Huber..... 39
Blast Furnace Obstructions, The Use of Oxygen in Removing 590
Blow-off Valve, Hopkinson's Boiler 360
Blue Black, For Coloring Brass. H. M. Weber..... 661
Blue Gun Barrels, To. F. L. Engel 424
Blue Printing Apparatus, Novel. H. O. Garman..... 314
Blue Printing Formula. R. B. Otis 102
Blue Prints, Chemicals for. D. Melville 102
Blue Prints, Formula for Red and White Writing Solutions for (H. & W. 3)..... 206
Blue Prints from Bristol Board Originals, To Make. R. F. Kiefer 420
Blue Prints from Typewritten Originals, Making. C. J. M. 367
Blue Prints from Typewritten Originals, Making. W. H. A. 264
Blue Prints, Mounting. W. W. W. 486
Blue Prints, Photographic Reproduction of 525
Blue Prints, Solution for Writing on. G. V..... 545
Blue Prints, To Bleach. F. Dibelius 490
Blue Prints, To Make Changes and Corrections on. R. F. Kiefer 424
Blue Prints, White and Red Solutions for Writing on. E. H. Remde 373
Blue Prints, White Writing Fluid for, C. W. Morrison. 323
Bluff That Got Called, The. A. P. Press 535
Bluing Brass, Solution for. T. E. O'Donnell 606
Bluing for Laying Out Work. F. G. Sterling 322
Boehler, G. W.:
What the Brass Checks Say 598
Boiler, A Dangerous. C. E. Mink 203
Boiler Bag, How Loose Scale Caused a 350
Boiler Draft Production..... 25
Boiler Making in the United States 52
Boiler Plant Economy..... 304
Boiler Trouble Due to Faulty Design 388
Bolts with Hand Dies, Threading Oversize. R. M. Harris. 605
Border Line Pen. A. P. Sharpe 598
Boric Acid and Sodium Carbonate Used in Hard Soldering or Brazing 101
Boring Bar Cutters. M. S. W. 599
Boring Bar for Boring Taper Holes. Texas 321
Boring Bar, Spherical. Ward. 597
Boring Mill Fixtures for Turning and Boring Steam Pump Liners. C. P. L.... 371
Boring or Facing Bar. C. V. Kinsman 322
Boring Rig, Special 522
Boring Tools. W. J. Kaup.. 89
Bossert, C. P.:
Loose Pulley Bearing..... 368
Bowen, E. W.:
Casting out the "Nines" to Prove Multiplication and Addition 656
To Make Van Dyke Prints Transparent 661
Brake Band, Necessary Tension in (H. & W. 12)..... 324
Brakes. 1. C. F. Blake.... 619
Brass Blue Black, For Coloring. H. M. Weber..... 661
Brass, Brightening and Coloring. J. M. Stabel..... 597
Brass Checks Say, What the. G. W. Boehler 598
Brass, Cleaning Solution for. R. M. K. 661
Brass, Compound for Cleaning. G. E. Hetzler 323
Brass, Copper and Bronze, Bright Dip for. S. H. Sweet 154
Brassing Iron. R. B. Casey.. 154
Brass or Bronze on Iron, Casting 83
Brass or Copper with Tin, To Coat. H. C. 490
Brass or Steel to Steel, To Solder. Carroll Ashley ... 204
Brass, Preparing Dead Surfaces on 83
Brass Small Articles, To. R. M. 373
Brass, Solution for Bluing. T. E. O'Donnell 606
Brass Valves Leak, Why..... 407
Braze Cast Iron Successfully, To 592
Braze Steel and Iron without Heat, To. J. M. Stabel.... 661

Bridge Model, Construction of a. Jarvis A. Marikle..... 553
Bright Dip for Brass Castings 471
Bright Dip for Brass, Copper and Bronze. S. H. Sweet.. 154
"Bristol":
To Caseharden Locally.... 372
Hardening Transmission Chain Pins 599
British Improvement in Hand Reamers 134
Broaching Die, A. T. J..... 659
Bronzing Fluid for Steel. "O. G." 545
Brown, R. S.:
Index for Pocketbooks.... 542
Brown & Sharpe Cutter Grinder for Grinding Snap Gages, Arranging a..... 403
Brutsche, A. J.:
A Gas Engine Cylinder Jig. 202
Buckling Strain Tests on Round Rods with Clamped Ends 456
Buffing Wheels and Grindstones, Speed of. J. A. Pratt 541
Builders' Chalk for Scraping and Testing. A. L. Monrad 423
Buildings Reduced to Marketable Materials 405
Burbank, L. S.:
Mixture for Making Plug Cocks Tight—Same for Glass Stoppers 205
Burbank Quick Change Gear, The 480
Burgess, Milton:
Copper Coating Solution.... 373
Cut-off Tool for Thin Brass Tubing 423
To Drill Hardened Steel.... 488
To Turn Rubber 488
To Solder Small Pieces Together. Notes on Soldering 489
To Preserve Reference Tables 545
Burlingame, L. D.:
The Figuring of Gear Drawings 623
Burns, Geo. J.:
High Speed Planer..... 34
Burnt Oil from Hardened Steel, To Remove. H. J. Bachmann 268
Burnt Steel, To Restore. "A. A." 205
Bursting of Emery Wheel Causes Death of Man..... 315
Bursting Strength of Cast Iron Cylinders, The. C. H. Benjamin 120
Bushes, Method of Machining. S. J. Fisher 152

Cable for New Cunarders, Heavy Chain 511
Calcium Steel 525
Calorium 249
Can Bottom Punch and Die. W. Van Orman..... 466
Cantilever, Quebec 175
Capacity of Steam Hammers and the Horse Power Required for Operation, Rules for Finding. L. N. Gillis.. 370
Capstan Head Screws and Nuts, Turret Tools for Drilling Holes in. C. V. Raper. 141
Cardullo, F. E.:
Choice of a Factor of Safety for a Machine Member... 221
Strength and Ductility of Steel 556
Carmania, The 240
Carr, L. C.:
Aluminum Solder 661
To Punch Hard Rubber... 661
Cartridge Cases for Quick-firing Guns, The Drawing of 228
Cartridge Shells, Steps and Press Employed in Making Rapid-fire 190
Car Wheel, Elastic Cast Iron. 81
Case, A Pocket Instrument. H. L. Millar 46
Case-Harden Cast Iron, To. J. M. Menegus 606
Case-Hardening Ring Thread Gages. E. Kneen 605
Case-Hardening, To Imitate. H. Ash 154
Case-Harden Locally, To. "Bristol" 372
Casey, R. B.:
A Die Socket..... 45
To Anneal Steel or Iron... 102
Brassing Iron 154
To Scale Cast Iron..... 323
Casting Brass or Bronze on Iron 83
Casting in Metal Moulds..... 30
Casting from a Broken One, To Make a Simple. J. W. Wilford 488
Casting Ladle, Lobdell Air.. 166
Casting Out the "Nines" to Prove Multiplication and Addition. E. W. Bowen... 656
Castings from the Patterns, Estimating the Weight of... 81
Castings, Pickling 648
Cast Iron Beams, Sections of. C. H. Benjamin 437
Cast Iron, Copper Plating. A. L. Monrad 606
Cast Iron Cylinders, The Bursting Strength of. C. H. Benjamin 120
Cast Iron, Expansion of..... 25
Cast Iron, Cement for. A. A. 205
Cast Iron Successfully, To Braze 592
Cast Iron, To Case-Harden. J. M. Menegus 606
Cast Iron, To Scale. R. B. Casey 323
Cast Iron, To Toughen and Surface Harden. J. H. V. 545
Caution 107
C. B.:
High Speed Drill for Spindle Forgings 147
C. E. J.:
Chip Guard for Lathe Tools 544
Cells Required to Run ¼ H. P. Motor at 110 Volts (H. & W. 7) 206
Celluloid, Mending Cements for. F. L. Engel..... 268
Celluloid Protector for Drawings. R. A. Lachmann.... 483
Celluloid Protractors, Warping of (H. & W. 5)..... 206
Celluloid, To Write on. J. M. Menegus 661
Cement for Attaching Metal to Glass. R. M. K..... 661
Cement for Attaching Soft Rubber to Iron or Other Metals. M. E. Canek 205
Cement for Belts. J. M. Menegus 606
Cement for General Use, Cheap. J. H. V. 490
Cement for Leather Belts. O. E. Perrigo 424
Cement for Mending Broken Porcelain 386
Cement, Glycerine-Litharge. O. E. Voris 661
Cement, Iron. D. Melville.. 102
Cement on Grinder Disks, Substitute for. G. Huber.... 268
Cement, Water and Oil Proof. Albert Elmiger 205
Cement, Waterproof 596
Centering Device, Drill Press. E. G. Eberhardt 265
Centering Device for Screw Machine. Gerrold Howard.. 38
Center Punch, A Self-Centering. Calvin B. Ross 201
Center Punch, A Self-Centering. Clay-Bean 369
Center Reamers, Hollow Grinding. H. Ash 45
Centrifugal Force, Calculating. W. H. Acker 648
Centrifugal Pump 305
Centrifugal Stresses, Systematic Method of Computing. S. A. Moss 7
Chain Drive to Replace Governor Belt 81
Changeable Height Blocking, Clamp with. M. Dehne.... 149
Change Gears, Spring Nut for. 613
Chapped Hands, For. G. C. Nash 323
Chapping in Winter, To Prevent Hands. F. H. Jackson 205
Chart, Bevel Gear. Geo. J. Porter 18
Chart, Power Transmission. R. N. Dull 60
Check Valve for Unobstructed Flow of Liquid 95
Chemical for Blueprints. D. Melville 102
Cheney, J. V. N.:
Lining Connecting Rods.... 416
Chicago Freight Tunnels..... 189
Chilled Cast Iron, To Drill (H. & W. 17)..... 425
Chimney Construction, Concrete for 116
Chinese Government's First Patent 25
Chip Guard for Lathe Tools. C. E. J. 544
Chips from Jigs and the Like, To Remove Steel. F. Pavlik, Jr. 545
Christmas Greetings..... 186
Chrome Nickel Steel..... 388
Chucking Pieces for Planer Work. A. F. Bierbach.... 322
Circular Section, Table of Moduli of. O. E. Thaleg..... 150
Circular Track for Lathes Used for Heavy Faceplate Work.. 398
Circumference Rule, Using a Metric Tape as a. Winamac 605
Circumferential Speed for Circular Saw..... 478
C. J. M. Making Blueprints from Typewritten Originals. 367
C. J. S. A Handy Belt Shifter 149
Clamping Cylinders, Hydraulic. F. B. Kleinhans..... 121
Clamping Facilities in Machining Large Work, Importance of Good..... 33
Clamp with Changeable Height Blocking. M. Dehne..... 149
Clarify Shellac Varnish, To. O. E. Perrigo..... 373
Clay-Bean. A Self-Centering Center Punch..... 369
Claying Mixture for Forges, S. H. Moore..... 373
Cleaning Solution for Brass. R. M. K..... 661
Cleaning the Hands, Compound for. H. J. Bachmann..... 154
Cloth to Iron, Attaching. J. A. Pratt 102
Clutch and Loose Pulley, A Combined. C. E. Mink.... 98
Clutch, Toothed. A. Gottschalk 600
Coal Cars, Unloading..... 63
Coal, Heating Capacity of.... 81
Coal Producer Gas Engine, Test on..... 585
Coals, Series of Tests on.... 585
Coating Gray Iron Castings with Tin. (H. & W. 1).. 103
Cocks in Steam Gage Pipes, Danger of..... 103
Coil Springs, To Increase the Working Length of. Winamac 660
Coil Springs, To Temper Small. A. L. Monrad 424
Colburn Mch. Tool Co.'s Shop. 281
Cold-Water-Anneal Tool Steel, To Successfully. C. F. Emerson 101
Coleman, J. W. Triangle for Drawing Threads..... 655
Collapsing Pressures of Bessemer Steel Lap-Welded Tubes 506
Color on a Drawing That is to be Varnished, To Write With. H. L. Millar..... 490
Colt's Automatic Army Pistol, The Manufacture of..... 457
Combination Drill Jig with Movable Leaves. L. J. G.. 656
Combination Threading Tool. E. Kneen..... 659
Compass Made in America, First Surveyor's..... 296
Concentrating Power to Reduce Smoke..... 132
Concrete Construction..... 524
Concrete Floors in Factories.. 36
Concrete for Chimney Construction 116
Concrete Skyscraper, First... 371
Condensing Plants for High Vacuums.
1 77
2 130
Cone Pulley Radii. John J. Harman. 9
Connecting-Rod Bolts for Gas and Oil Engines..... 135
Conradson Speed Box, The... 257
Contributions, Syndication of.. 641
Con Wise:
Choosing an Employer..... 576
Coombs, H. A.:
Early Buildings of the Skeleton Type..... 338
Copper Chucking Strips for Lathe Chucks. Robt. Mayhew 417
Copper Coating Solution. M. Burgess 373
Copper Plating Cast Iron. A. L. Monrad 606
Copper, The Tempering of.... 44
Copying Illustrations of Printed Matter 469
Cord-Knotter of the Self-Binding Harvester, The Evolution of the..... 643
Cornstarch Preferable to Chalk in Die-Makers' Wax..... 142
Correction, A..... 6
Cost Estimating. H. T. M... 368
Cost of Lathe Work, Finding the. C. D. Salisbury.... 484
Cost of Machine Work, Data Upon 80
Cost of Machine Work, Estimating the. H. L. Millar.. 99
Cotton Industry from North to South, Shifting of the..... 256
Counterbores, Proportions of. A. Anderson 146
Counterboring Tool, Shell. O. L. Lewis 151
Countersink in Mandrel for Taper Work, Curved Side. M. H. Ball..... 101
Country Machine Shop. R. E. F. 649
Coupling, The "Short." C. E. Mink 261
Courter, Stephen:
Threading Tool Holder for High Speed Steel..... 660
Court Plaster, Liquid, F. H. Jackson 205
Cowper-Coles Galvanizing Process 192
Cowper-Coles Process of Galvanizing 133
Coyne, James F.:
To Harden Tools Without Danger from Fire Cracks 45
C. P. L.:
To Prevent Tools Rusting.. 322
Boring Mill Fixtures for Turning and Boring Steam Pump Liners..... 371
To Treat Foreign Matter in the Eye..... 372
Chalk as a Lubricant for Lathe Centers..... 544
Crab Couplings 532
Crank Pin, Which is Held too Firmly, From Its Disk, Removing a..... 63
Credit Belonging to Max J. Oches Erroneously Given to Max Dehne 425
Crocker-Wheeler-Terry Turbo-Generating Set 35
Crocker-Wheeler Works, A Floor Plate Boring Mill at the 112
Cross-Planing a Gap-Lathe Bed. W. L. Fay 147
Cross-Planing Gap Lathe Beds. E. H. Fish..... 200
Crowning Pulley. G. A. Gauthier 42
Crystallography in the Study of Materials of Construction, the Importance of..... 624
Cunarders, Heavy Chain Cable for New 511
Cunard Liner, The Turbine-Driven 311
Curie, Death of Prof..... 518
Curtis Steam Turbine, Test of 357
Curved Side Countersink in Mandrel for Taper Lathe Work. M. H. Ball..... 101
Cut-Off Tool for Thin Brass Tubing. Milton Burgess... 423
Cutter Grinder for Rotary Planers 385
Cutter Holder for Slotter. G. E. White 203
Cutters Accurately on the Universal Milling Machine, Setting. W. C. Force..... 320
Cutters, Boring Bar. M. S. W. 599
Cutters for Taps and Chucking Reamers, Thickness of. J. A. P. 543
Cutters of Cold-Rolled Steel. F. Wackermann 602
Cutter to Reduce Tool-Making Cost, Evolution of a. A. C. Lindholm 601
Cutting a Gear in a Lathe. Jas. McCarthy..... 655
Cutting a Traverse Screw.... 95
Cutting Spiral Gears. E. H. Fish 65
Cutting Spirals on the Plain Milling Machine, Fixture for. Hamilton Rice..... 41
Cutting Thread in Tool Steel, Lubricating Mixture for, E. Kneen 661
Cutting Tools, Hardening Formula for. Toolmaker..... 606
Cutting Tools Sharp, Keeping. H. L. Millar 96
Cylinders, Thick. J. S. Holliday 13

Danger of Railway Traveling.. 25
Data Sheet, Correction to December 386
Data Sheet, December..... 193
Data Sheet, Error in October. 322
Data Sheet, February..... 312
Data Sheet for November..... 116
Data Sheet No. 48, To Bind. H. E. Twomley..... 374
Data Sheet, October..... 88
Data Sheets, Grouping Machinery's. K. B..... 100
Data Sheet 48 Was Made An Odd Size, Why (H. & W. 6) 206
Dead Surfaces on Brass, Preparing 83
December Data Sheet 193
Deception That Did Not Work, A. H. T. M..... 265
Deep-Hole Drill, Construction of a. E. W. Norton..... 93
Deep-Hole Drills Twenty Years Ago, How I Made. F. N. Gardner 317
Dehne, Max:
Clamp with Changeable Height Blocking..... 149
Alloys for Drawing Colors on Steel 323
De Leeuw, A. L.:
Comment on "Milling Cutters" 485
Problem of Touching Circles 444
Surveying Without Instruments 565
De Leeuw's (A. L.) Office in Hamilton 373
"Denatured" Preferred to "Denaturized" 641
Denaturized Alcohol..... 404
"Denaturized" Alcohol..... 195
Denaturized Alcohol, Untaxed. 471
Depths of U. S. Standard and V-Threads 206
De Sanno, W.:
Patching Tires..... 421
Designing and Building a Machine Part. H. P. Fairfield 571
Designing Two Point Ball Bearings 384
Design of a Riveted Joint. F. H. Smith..... 387
Design of Billet and Bar Passes, The. B. H. Reddy 451
Design of Large Gas Engines with Special Reference to Railway Work, Notes on the 138
Detachable Link Driving Chains, Horse Power of. W. O. Renkin 202
Detecting Leaks in the Vacuum System of Compound Engines 108
Diagram for Computing the Time to Take Lathe Cuts.. 16
Dialing, Elementary. Jas. Arthur 509
Dibelius, F.:
To Bleach Blueprints..... 490
Die, A Broaching. T. J..... 659
Die, An Adjustable—An Angle Cut-off. J. L. Lucas..... 151

193654

Die Makers' Square, Two Toolholders and a. C. Ashley.. 43
Die, Making a Blanking. C. F. Emerson 516
Dies, Backing-off Spring and Button, J. S. Scott 543
Diesel Oil Engines, Cost of Fuel for..... 469
Dies for Threading Steel Pipe, Shape of..... 82
Die Sinkers' Impression Wax. C. W. Shelley..... 102
Die Socket, A. R. B. Casey.. 45
Dies, Spring Screw Threading. E. Oberg 625
Dividing Fractions by Two, Method of. L. F. Lang.. 660
Division, A Kink in. Robt. Grimshaw 425
Dogs and Drivers, Some. P. W. Abbott 658
Don't, A..... 461
Don't, A..... 365
Don't, A Planing..... 613
Don't File Out a Hole, Etc.. 372
Don'ts for Machinists, Practical. H. E. Wood:
2 231
3 316
Don'ts, Machine Shop..... 304
Don'ts, More Draftsmen's. F. G. Kenyon..... 538
Drafting Room of the B. F. Sturtevant Co..... 1
Drafting Room Practice. Robt. Grimshaw 19
Drafting Room practice, Patching Drawings. W. G..... 238
Drafting Room, Time Saving in the. F. R. Steuart..... 655
Drafting Tool for Sketching Ratchet Teeth, etc. Handyman 604
Draft Production, Boiler..... 25
Draftsman and his Work, The. J. L. Lucas..... 14
Draftsman's Device for Drawing Letter Space Lines. F. W. Bach 541
Draftsman, The Advantage of Practical Shop Training for the. H. J. Bachmann.... 41
Draftsmen, Hard Lines for. H. E. Wood..... 73
Draftsmen, Instructions for. E. W. Beardsley..... 11
Draftsmen, Kinks for. E. W. Beardsley 38
Draftsmen, Rules for..... 463
Draftsmen's and Designers' Kinks, Some. Handyman.. 537
Draftsmen's Number of Ma-Machinery 24
Draft, The Creation of..... 145
Draw-In Chuck for Engine Lathes. C. J. Shaw..... 419
Drawing of Cartridge Cases for Quick-Firing Guns, The.... 228
Drawing Press, A New..... 194
Drawing Room Instrument Holder, A. C. P. Thiel.... 44
Drawings, Method of Enlarging or Reducing. Winamac 657
Drawing Table for Tracing Blueprints. R. F. Kiefer.. 540
Drill and Counterbore or Facing Tool, Combination. R. A. Lachmann 204
Drill and Mill, Grinding a Combination Flat. F. G. Sterling 604
Drill, A Pendulating Electric. Dr. Alfred Gradenwitz..... 20
Drill Chilled Cast Iron, To (H. & W. 17)..... 425
Drill Hardened Steel, To. M. Burgess 488
Drill Hard Steel, To. G. E. Hetzler 424
Drill, Holding the Work on a Horizontal Multiple Spindle —"B" 262
Drilling and Assembling Jig. H. J. Bachmann..... 201
Drilling Compound. F. Pavlik, Jr..... 102
Drill Jig with Movable Leaves, Combination. L. J. G.... 656
Drill-Press Centering Device. E. G. Eberhardt..... 265
Drills for Cutting Glass, To Harden. E. W. Norton.... 606
Driver for Twist Drill, Extemporized. C. F. Emerson 604
Drivers, Some Dogs and. P. W. Abbott..... 658
Drive, The Geared..... 24
Drydock Dewey to its Destination, Towing the..... 642
Dry Grindstone, Stronger Than When Wet..... 108
Dull, R. N.:
Power Transmission Chart.. 60
Dynamite, Destructive Action of 249
Dynamotor or Motor Generator Used to Charge Storage Batteries (H. & W. 7).... 206

Eberhardt, E. G.:
Drill Press Centering Device. 265
Eckart, W. R..... 511
Eckelt, Otto.:
Finding the Size of Blank for a Cup 320
Method of Finding Pitch Angle of Bevel Gears..... 419
Economizers Results in a Number of Plants of B. F. Sturtevant 338
Edgar, John.:
The Worm Gear..... 63
Edition, A Large..... 662
Editorial Change..... 584
Edo Shock Absorber..... 653
Education of Foremen..... 240
Eight-Inch Finishing Rolls, Grinding. W. T. M..... 152
Elastic Cast Iron Car Wheel 81
Electric Drive, The Simplicity of the..... 258
Electricity? What is 366
Electric Train Haulage, Progress and Future of..... 133
Electro-Deposition 133
Electromagnetic Guns..... 470
Electron 312
Elemental Substances Divided or Resolved Into New Forms 249
Ellipsograph, An..... 37
Elmiger, Albert:
Water-and-Oil-Proof Cement 205
Emerson, C. F.:
To Successfully Cold-Water-Anneal Tool Steel..... 101
To Prevent Blanking Dies From Excessive Warping in Hardening..... 204
Lubricants for Redrawing Shells 205
Making a Blanking Die.... 516
Extemporized Driver for Twist Drill 604
Emerson, F.:
Marking Paint..... 102
Bicycle Tire Anti-Leak..... 204
Emery Cloth to Polishing Disk, To Cement. O. E. Perrigo 545
Emery for Lapping Gages, To Prepare. A. L. Monrad.... 372
Emery Paper on Small Grinder Disks, Cement for Sticking. H. J. Bachmann..... 154
Emery Wheel Don't, An..... 522
Emmons, S. E.:
The Engineers' Department of a Large Hotel..... 70
The Bell Industry..... 515
Employee's Intelligence in Executing Orders..... 583
Employe, Independence of.... 44
Employer, Choosing an. Con Wise 576
End Mill, "Hurry Up." L. E. Muncey 101
Engel, F. L.:
Cements for Iron Joints.. 154
Mending Cements for Celluloid 268
Waterproof Paint for Plaster 323
To Blue Gun Barrels..... 424
To Remove Grease Stains from Papers, Drawings, Etc. 545
Engine Cranks, Filing up. Jno. D. Riggs..... 198
Engineering Building..... 255
Engineering Reports as Advertisements 586
Engineer's Commentary on His Own Work, An..... 523
Engineers' Department of a Large Hotel, The. S. E. Emmons 70
Engine Lathe, An Ancient. H. P. Fairfield..... 367
Engine Lathe, Setting Up An. Robt. Mayhew 198
Enlarging or Reducing Drawings, Method of. Winamac 657
Entering Wedge, The..... 468
Entropy:
A Few Items Which Have Helped Me..... 100
Heroic Methods of Doing Work 199
The Apprenticeship Question 629
Visiting Shops..... 76
Envelope System for Filing Data. C. E. Josselyn.... 542
Error in Article "Free Alcohol and Its Effect on Industrial Conditions" 641
Error in Circulation Statement Corrected 132
Error in Formula for Horse Power Transmitted by Belting 641
Errors in Data Sheets, Information Requested Regarding... 248
Errors in Machinery Data Sheets 240
Espionage and the Honor Systems, The..... 136
Estimating, Cost. H. T. M.. 368
Estimating the Cost of Machine Work. H. L. Millar 99
Estimating the Cost of Work, Hints on. H. K. Griggs.. 97
Estimating the Weight of Castings from the Patterns.... 81
Estimating Time on Machine Work. J. H. VanYorx, Jr. 289
Etching, Acids for. E. W. Norton 490
Etching Fluid. S. C. 205
Etching Fluid for Steel. W. S. Leonard..... 373
Etching on Hardened Steel, For. A. S. Gun..... 268
Evolution of the Cord-Knotter of the Self-Binding Harvester 643
Exaggerations of the Daily Press 596
Exhausting Arrangement for Grinding and Polishing Wheels 402
Exhaust Muffler for Gas Engines, Weiss 479
Exhaust Muffler, Simple Gas Engine 188
Exhaust Silencer or Muffler.. 586
Expansion of Cast Iron..... 25
Explosive Liquids, Safe Storage of 189
Extruded Metal Sections 650
Eyes, To Treat Inflamed, Care of the. C. Ashley..... 154
Eye, To Treat Foreign Matter in the. C. P. L..... 372
Eye-Wash. Geo. C. Nash.... 323
Eyles, A.:
To Solder Aluminum..... 606

Facing Fixture, Rod Brass. I. N. Quire 544
Factor of Safety for a Machine Member, Choice of a. F. E. Cardullo..... 221
Factor of Safety to Determine Thickness and Width of Driving Belt 187
Factory Education. O. M. Becker.
1 163
Fairfield, H. P.:
An Ancient Engine Lathe.. 367
Shop Visitors — Rolling in Babbitt — Planer Tool Lifter 537
Designing and Building a Machine Part 571
Falk, E. C.:
Ink Eraser and Thumb Tack Puller 605
Fan as an Absorption Dynamometer 249
Fan-Blower Design, Conditions of 441
Fans. C. L. Hubbard.
1 49
2 109
3 165
Fans, Volumetric Capacity of.. 26
Fastening for Bank Window Grating 415
Fay, W. L.:
Cross-Planing a Gap-lathe Bed 147
How a Coarse Pitch Screw Was Cut..... 600
Feed or other Water Pipe Temporarily, To Repair. J. A. Pratt..... 101
Female Work in the Foundry 532
Figuring of Gear Drawings. L. D. Burlingame..... 623
File, How He Cut Off the. A. P. Press..... 232
Filing Data, Envelope System for. C. E. Josselyn..... 542
Filing in a Bicycle Shop..... 133
Filing Machine..... 63
Filing Up Engine Cranks. Jno. D. Riggs..... 198
Fillets and Round Corners, Estimating Weights of..... 592
Fire-Cracks, To Harden Tools Without Danger From. J. F. Coyne 45
Fire Fighting Apparatus, Importance of..... 570
Fire Protection..... 584
"Firsts" 187
Fish, E. H.:
Cutting Spiral Gears..... 65
Cross-Planing Gap Lathe Beds 200
The Teaching of Mechanical Drawing 384
Fisher, S. J.:
Method of Machining Bushes 152
Fitting and Scraping, Paint for. F. W. B. 102
Flame, Temperature of..... 250
Flanders, R. E.:
On the Location of the Pitch Circle in Worm Gearing.. 122
Method of Procedure in the Design of Helical Gears.. 453
Flexible Curves for Draftsmen. R. Grimshaw..... 265
Flint-lock Muskets Made in Birmingham 81
Floor Plate Boring Mill at the Crocker-Wheeler Works, A.. 112
Floorplate Work in the Allis-Chalmers Shops 627
Flywheel Accident at Memphis Caused by the Loosening of the Pillow-block 25
Flywheel Job, A..... 365
Flywheel of a Steam or Gas Engine, Mounting of a.... 356
Flywheel or Gear Not Affected by the Number of Spokes in the Wheel, Shrinkage of Arms of a (H. & W. 9)..... 324
Flywheel, Sixty-Ton..... 562
Food Supplies for Large Towns, Distribution of.... 525
"Forced Draft" in Naval Machinery 470
Force, W. C.:
Setting Cutters Accurately on the Universal Milling Machine 320
Foreign Matter in the Eye, To Treat. C. P. L..... 372
Foreign Patents 68
Forming Lathe, A New..... 519
Formula, Blue Printing. R. B. Otis 102
Formula for Obtaining the Sine of an Angle Below 80 Degrees 81
Formulas and Constants for Gas Engine Design. S. A. Moss 287
Formulas, Two Useful. Alex. C. Labar..... 369
Foundry, A Plea for Better Surroundings in the..... 79
Foundry, Female Work in the 532
Foundry, The New Gisholt.. 68
Fractions by Two, Method of Dividing. L. F. Lang.... 660
Franklin, 200th Anniversary of the Birth of..... 336
Freak, A Shop. J. H. V..... 483
Freight Tunnels, Chicago..... 189
French, Roger D. L.:
Triangle for Drawing I-Beam Sections 96
Friction 67
Friction Gearing..... 223
Friction of Roller Bearings, The. C. H. Benjamin..... 62
Friction, The Law of 463
Frogs, Modern Methods in the Manufacture of..... 504
Frozen Gun Oil..... 133
Fuerle, R. H.:
Threading Attachment for the Speed Lathe 199
F. W. B.:
Paint for Fitting and Scraping 102

Gage, Parallel Vernier. O. Westberg 601
Gage, Plug and Ring, Dry vs. Lubricated. Perplexed..... 148
Gages, Cast Iron. I. N. Quire 489
Gages for Small Duplicate Work, A Set of Accurate Test and Inspection. J. V. Woodworth 73
Gaging Flow of Streams by Chemical Means..... 305
Galalith, A New Industrial Product 188
Galvanizing, Cowper-Coles Process of..... 133
Galvanizing Process, Cowper-Coles 192
Galveston, Difficulties Encountered by Street Railway in Raising the Grade of the City of..... 607
Gap-Lathe Bed. Cross-Planing. W. L. Fay..... 147
Gap Lathe Beds, Cross-Planing. E. H. Fish..... 200
Gardner, F. N.:
How a Knife-Edge Straightedge Was Made..... 128
How I Made Deep-Hole Drills Twenty Years Ago 317
Garman, H. O.:
Novel Blue Printing Apparatus 314
Gas and Oil Engines, Connecting-Rod Bolts for..... 135
Gas Boosters..... 357
Gas Engine and the Automobile, Patents in Their Relation to. S. M. Howell.
1 241
2 333
3 441
Gas Engine Cylinder Jig, A. A. J. Brutsche 202
Gas Engine Cylinders, Packing for. H. J. Bachmann..... 154
Gas Engine Design (H. & W. 19)..... 607
Gas Engine Design, Formulas and Constants for. S. A. Moss 287
Gas Engine Driven Generator, 4,000 K.W..... 67
Gas Engine Economy..... 473
Gas Engineering in the Orient. "Traveler" 235
Gas Engine Exhaust Muffler, Simple 188
Gas Engine, For Greater Economy of the..... 360
Gas Engine, Naval, M. Joachimson 578
Gas Engine, Power Developed by Large Four-Cycle 650
Gas Engines, Alcohol as a Fuel for 644
Gas Engines, Method of Balancing 406
Gas Engines with Special Reference to Railway Work, Notes on the Design of Large 138
Gas Engine, The Development of the 528
Gasholder in the World, Largest 557
Gasoline Engine Cylinders, Offsetting the Center Line of.. 357
Gasoline for Power Generation, Efficiency of 559
Gasoline Pumps, Packing for. A. A. 268
Gasoline vs. Denaturized Alcohol 470
Gas or Oil for Driving Turbine 188
Gas Producer and Boiler Plants, Comparing the Performance of 160
Gas Producer, Portable 444
Gas Producer Power Plant, The Economy of the..... 160

Gas Producer, Notes on..... 588
Gas Turbine, The 588
Gas Turbine, The Problem of the 359
Gate Valves, Manufacturing Large 568
Gauthier, G. A.:
Pulley Crowning 42
Gear Arms, Pulley and..... 6
Gear Drawings, The Figuring of. L. D. Burlingame..... 623
Geared Drive, The 24
Geared Drive, The. A. M. Sosa 367
Geared Drive, The J. C. Steen 195
Gear, Improvised Slip. Bessemer 598
Gear in a Lathe, Cutting. Jas. McCarthy 655
Gearing, Noisy 305
Gearing, Severe Requirements for Automobile 514
Gear Ratios, Changing. C. M. McElhany 371
Gear Ratios when the Number of Teeth and Center Distance is Fixed, To Change. C. E. Josselyn 99
Gear Wheels, Grease for. M. J. Oches 606
G. E. H.:
Split Worm Wheel 597
General Electric Co., West Lynn, Mass., Apprenticeship and Educational System of the 399
Generator, 4,000 K.W. Gas Engine Driven 67
German Outside Spring Indicators, Some. Dr. Alfred Gradenwitz 72
Gillis, L. N.:
Rules for Finding the Capacity of Steam Hammers and the Horse Power Required for Operation 370
Gisholt Foundry, The New.... 68
Glass Stoppers Tight, Mixture for Making. L. S. Burbank 205
Glass, To Harden Drills for Cutting. E. W. Norton.... 606
Gleason Generating Bevel Gear Planer 594
"Globoid" Worm Drive, The. Robt. Grimshaw 177
Glues and Cements 638
Glues which Resist Moisture. A. L. Monrad 545
Glycerine-Litharge Cement. O. E. Voris 661
Gold Dredges 26
Gold from Sea Water, Recovery of 203
Gold from Small Quantities of Amalgam, To Procure..... 405
Gottschalk, A.:
A Toothed Clutch 600
Gradenwitz, Dr. Alfred:
A Pendulating Electric Drill 20
Some German Outside Spring Indicators 72
Graduating a Scale on a Planer. Carroll Ashley... 39
Graffam, A. L.:
Waterproof Cements for Glass 424
Graves, W. D.:
To Repair Frost-Cracked Water Jackets 322
Gray Iron Castings with Tin, Coating (H. & W. 1)..... 103
Grease as a Lubricant..... 424
Grease Paint, etc., from Machinery, To Remove Hard. F. Pavlick, Jr. 373
Grease Stains from Papers, Drawings, etc., To Remove. F. L. Engel 545
Grease, Wire Rope—Grease for Gear Wheels. M. J. Oches. 606
Griggs, H. K.:
Hints on Estimating the Cost of Work 97
To Prevent Babbitt from Exploding 101
Heroic Methods in the Machine Shop 146
Grimshaw, Robert:
Drafting Room Practice.... 19
The "Globoid" Worm Drive 177
Flexible Curves for Draftsmen 265
Cheap Suction and Lead Hose 420
To Cut India Rubber..... 423
A Kink in Division..... 425
Mainspring Kinks 489
German Belt Shifter 538
Roll Corrugating Device.... 541
Picking Up Small Articles with the Tweezers 604
Grinder Disks, Substitute for Cement on. G. Huber 268
Grinding a Combination Flat Drill and Mill. F. G. Sterling 604
Grinding Eight-Inch Finishing Rolls. W. T. M..... 152
Grinding Wheels to Prevent Glazing, Dressing. O. L. Lewis 372
Grindstone Stronger than when Wet, Dry 108
Ground Glass, Imitation. Wm. Newton 204
Grouping Machinery Data Sheets. K. B..... 100
Gulf: Weak Steam Fitting... 486
Gun, A. S.:
For Etching on Hardened Steel 268
Gun Barrels, To Blue. F. L. Engel 424
Gun Barrels, To Remove Dents from 586
Gun Metal Finish. J. L. Lucas 606
Gun Oil, Frozen 133
Gun Recoil, Reducing..... 559
Guns, Rapid Wear of Modern. 357
G. V.:
Solution for Writing on Blue Prints 545

Hack Saw Blades, A Use for Broken and Worn-out. Harron 488
Hack Saw Can Do, What the Power 651
Hamburg, Immense Trade of. 642
Hammer, To Harden a. I. W. Antano 267
Hand Reamers. H. D..... 259
Hand Reamers, British Improvement in 134
Hands Chapping in Winter, To Prevent. F. H. Jackson... 205
Hands, Compound for Cleaning the. H. J. Bachmann.. 154
Hands, Mixture for Cleaning Grimy. M. E. Howe..... 606
Hand Taps in Sets, Proportions of. H. D. 185
Hand Taps, The Proportions of. A. A. 96
Handyman:
Some Draftsmen's and Designers' Kinks 537
Drafting Tool for Sketching Ratchet Teeth 604
Harden and Temper Thin Circular Saws without Warping, To. S. C. Smith..... 482
Hardened Steel, Etching on. A. S. Gun 268
Hardened Steel, To Remove Burnt Oil from. H. J. Bachmann 268
Hardening a Scratch Awl. R. A. Lachmann 101
Hardening Formula for Cutting Tools. Toolmaker 606
Hardening, Hints on. L. S. B. 322
Hardening Milling Cutters. (H. & W. 8)..... 206
Hardening without Cracking. F. E. Shailor 318
Hardening without Cracking. H. J. Bachmann 542
Harden Tools without Danger from Fire Cracks, To. J. F. Coyne 45
Hard Lines for Draftsmen. H. E. Wood 73
Hard Soldering or Brazing, Boric Acid and Sodium Carbonate Used in 101
Harman, John J.:
Cone Pulley Radii 9
Harris (Emerson P.) on Trade Journalism 466
Harris, Roy W.:
Threading Oversize Bolts with Hand Dies 605
Harron:
A Use for Broken and Worn-out Hack Saw Blades... 488
Harvester, Evolution of the Cord Knotter of the Self-Binding 643
Hatchet Planimeter, Beam Compass Converted into a. E. J. Lees 264
Hatchet Planimeter, The..... 28
Hatchet Planimeter, Theory of the 530
H. C.:
To Coat Brass or Copper with Tin 490
To Remove Grease or Dirt from Mercury 606
H. D.:
Relief of Taps 75
Proportions of Hand Taps in Sets 185
Hand Reamers 259
Rules for Draftsmen 462
Heated Piston Engine, A. Chas. R. King 381
Heat Generated by Coal..... 187
Heating and Ventilating System Installed in New U. S. Custom House 634
Heating Capacity of Coal.... 81
Heating Coil Connection to an Exhaust Steam Line..... 405
Heating Power of the Waters of Niagara 633
Heating Problem, A 568
Heating, Salt Bath for. Jas. A. Pratt 544
Helical Gears, A Method of Procedure in the Design of. R. E. Flanders 453
Helped Me, A Few Items Which Have. Entropy 100
Heroic Methods in the Machine Shop. H. K. Griggs. 146
Heroic Methods of Doing Work 132
"Heroic Methods of Doing Work." Entropy 199
Hetzler, G. E.:
Compound for Cleaning Brass 323
To Drill Hard Steel..... 424
H. H. G.:
To Level Up a Lathe..... 483
High Prices Ninety Years Ago 32
High Speed Bearings, Lubricant for. H. J. Bachmann. 268
High Speed Drill for Spindle Forgings. C. B. 147
High Speed Planers. Geo. J. Burns 34
High Speed Steel, Acid to Dissolve (A. to H. & W. 57). A. A. 46
High Speed Steel Drills for Drilling Rails with Ratchet or Hand Drilling Machine.. 145
High Speed Steel Punches, Superior Efficiency of 586
High Speed Steels, The Manipulation of. W. J. Todd.. 313
High Speed Steel, Threading Tool Holder for. S. Courter 660
High Speed Steel, To Anneal. I. W. Antano 153
High Speed Tool Steels on Cast Iron, Tests of..... 409
High Vacuum, Improvement in Process for Obtaining..... 102
High Vacuums, Condensing Plants for:
1 77
2 130
Hillix, Foster:
Template for Stamping with Steel Letters 372
History of the Marine Turbine 296
Hoefer Mfg. Co., New Shop of the 171
Holding the Work on a Horizontal Multiple Spindle Drill. "B." 262
Holliday, J. S.:
Thick Cylinders 13
Hollow and Solid Shafting, Table for Computing..... 20
Hollow Grinding Center Reamers. H. Ash 45
Hollow Mill and Jig, A. Chas. Thiel 263
Hollow Mill, Novel. E. W. Norton 484
Homestead (Pa.) Club House, Views of the 440
Honor Systems, The Espionage and the 136
Hopkinson's Boiler Blow-off Valve 360
Horse Power of Detachable Link Driving Chain. W. O. Renkin 202
Horse Power of the Niagara River 52
Horse Power Transmitted by Belts. F. Wackermann ... 559
Horse Power Transmitted by Wire Rope Drive, Estimating the 585
Hose, Cheap Suction and Lead. Robt. Grimshaw 420
Hose Coupling, Proposed Standard 587
Hotel, The Engineers' Department of a Large. S. E. Emmons 70
Howard, Gerrold:
Centering Device for Screw Machine 38
Howard, H. F.:
Ratchet Stop Handle for Milling Machine Vises... 370
Howell, S. M.:
Patents in their Relation to the Gas Engine and the Automobile—
I. 241
II. 333
III. 441
Howe, M. E.:
To Keep Steel Tools in their Handles 545
Mixture for Cleaning Grimy Hands 606
H. T. M.:
A Deception That Did Not Work 265
Cost Estimating 368
Hubbard, C. L.:
Fans—1 49
2 109
3 165
Huber, G.:
Substitute for Cement on Grinder Disks 268
Huber, H. R.:
Making a Blanking Punch and Die 39
Hunt, W. P.:
Weak Hydraulic Fitting ... 540
"Hurry Up" End Mill. L. E. Muncy 101
Hydrant Nozzles, Confusion of Sizes of 508
Hydraulic Clamping Cylinders. F. B. Kleinhans 121
Hydraulic Fitting, Weak. W. P. Hunt 540
Hydrofluoric Acid as a Cleaning Agent for Castings 405
Hydrolithe to Generate Gas for Balloons 585
I-Beam Sections, Triangle for Drawing. Roger De L. French 96
Ice Automobile, An 406
Ice-making Plant 76
Imitation Ground Glass. Wm. Newton 204
Incandescent Electric Lighting in Shops and Factories.... 508
Indentured Apprentices 24
Independence of Employe 44
Index for Eleventh Vol. of "Machinery" 24
Index for Pocketbooks. R. S. Brown 542
Index System—A 15
India Rubber, To Cut. Robt. Grimshaw 423
Industrial Betterment 186
Industrial Education, An Experiment in. O. M. Becker. 225
Industrial Engineering, The Realization of Ideals in.... 252
Inertia, One Effect of 640
Ingersoll Milling Machine Co., The Concrete Erecting Shop of the 446
Ingot, Largest Steel 469
Ink-Bottle Holder, An. W. O. Moody 541
Ink-bottle Holder, An. D. C. Turnbull 45
Ink Eraser and Thumb Tack Puller. E. C. Falk 604
Ink Lines from Tracings, To Remove. C. B. Ross..... 420
Ink, Motion of Particles in... 577
I. N. Quire:
Cast Iron Gages 489
Rod Brass Facing Fixture.. 544
Jackscrew with Extension Base 604
Fixture for Splining Keyway in Taper Hole of Pinion. 654
Inserted Tooth Cutter. G. E. White 267
Instantaneous Photography.... 248
Instructions for Draftsmen. E. W. Beardsley 11
Instrument Case, A Pocket. H. L. Millar 46
Instrument Holder, A Drawing Room. C. P. Thiel 44
Insulation, New 187
Interborough Rapid Transit Co. Test of Subway Engines.. 348
Inter-Pole Electric Motor.... 470
Interrupted Threads Taps, Lathe Rig for Making. W. Loach 39
Invar Used for Shop Standard Gages 469
Inventions, On Promoting.... 304
Invisible Platinum Wire..... 193
Iron and Marble, Cement for. R. M. 323
Iron and Steel, Acid Test for. A. A. 205
Iron, Brassing. R. B. Casey. 154
Iron Cement. J. W. Wilford. 490
Iron Cement. D. Melville.... 102
Iron, Danger of a Shortage in 526
Iron Joints, Cement for. F. L. Engel 154
Iron or Steel? J. M. Menegus 661
Iron or Steel Rust Proof, To Make. F. Pavlick, Jr. 423
Iron Rusting, To Prevent Exposed. Jas. A. Pratt 545
Iron, To Anneal Steel or. R. B. Casey 102
Iron was Rare, When 102
Iron Work, Varnish for. J. M. Stabel 661
Items Which Have Helped Me, A Few. Entropy 100

Jackscrew with Extension Base. I. N. Quire 604
Jackson, F. H.:
Use of Turpentine for Wounds 205
To Prevent Hands Chapping in Winter 205
Liquid Court Plaster ... 205
Rust Preventive for Tools.. 205
Jack's Trouble with His Engine 108
J. A. P.:
Thickness of Cutters for Taps and Chucking Reamers 543
Japanese Tariff 648
Japan, Patents in 134
J. C.:
Anti-Freezing Solution 323
Jewelry, Silverware and Metals, To Clean. P. B. Shee.... 545
J. H. V.:
A Shop Freak 483
Cheap Cement for General Use 490
To Toughen and Surface Harden Cast Iron 545
Non-Rusting Soldering Fluid 606
A Belt Cement 606
Jig, A Gas Engine Cylinder. A. J. Brutsche 202
Jig Bushings, To Harden Small. H. J. Bachmann... 153
Jim and His Drafting Room. A. P. Press 266
Joachimson, M.:
Naval Gas Engine 578

Johnson, Claude T.:
Tool for Laying Out Ratchet Teeth, Tangents, etc..... 597
Joke on the Old Man, A..... 414
Josselyn, C. E.:
To Change Gear Ratios when the Number of Teeth and Center Distance is Fixed. 99
Envelope System for Filing Data 542
J. S. S.:
Recessing Tool for Screw Machine 603
Jump of a Flea, High..... 296

Kaup, W. J.:
Boring Tools 89
K. B.:
Grouping "Machinery's" Data Sheets 100
Kenyon, F. G.:
More Draftsman's Don'ts.. 538
Keyseat in Nickel Steel Shafts, Closing a. Texas 148
Keyway Taper Hole of Pinion, Fixture for Splining. I. N. Quire 654
Keyways, Tool Support for Cutting Deep. R. A. Lachmann 45
Kiefer, R. F.:
To Clean a Tracing 369
To Make Blue Prints from Bristol Board Originals... 420
To Make Changes and Corrections on Blue Prints.. 424
Drawing Table for Tracing Blue Prints 540
Kinetograph, Curious Effect in a 525
King, C. D.:
An Unusual Method of Making Tubes 42
King, C. R.:
Ten Thousand Horse Power Rolling Mill Engine 217
A Heated Piston Engine... 381
Kinks for Draftsmen. E. W. Beardsley 38
Kinsman, Chas. V.:
Boring or Facing Bar..... 322
Kleinhans, F. B.:
Hydraulic Clamping Cylinders 121
Paper Scales 392
Knauel, A. D.:
Re-Inking Time Clock Ribbons 323
Riveting in the Turret Lathe 423
Whiting Surfaces for Laying-out Work 424
Lunch Room at the Rock Island Arsenal 637
Kneen, Everett:
Case-hardening Ring Thread Gages 605
Combination Threading Tool. 659
Lubricating Mixture for Cutting Thread in Tool Steel 661
Knife Edges, Permissible Loading for 642
Knife-edge Straightedge, The. Scotty 487
Knife-edge Straightedge Was Made, How a. F. N. Gardner 128
Knife with 75 Blades, Exhibition of 323
Knives Deflect Compass, Magnetized 661
Kroeger, Herrmann G.:
Tempering Compound for Steel 268
Anti-Friction Metal 268
Krupps Works, Extent of Business 248

Labar, Alex. C.:
Two Useful Formulas 369
Laboratory Training. C. H. Benjamin 291
Labor, What is Unskilled.... 132
Lachmann, R. A.:
Tool Support for Cutting Deep Keyways 45
Polishing Unfinished Surfaces 45
Hardening a Scratch Awl.. 101
To Start a Threading Die.. 101
Angle Plates to Extend Shaper Tables 204
Combination Drill and Counter Bore or Facing Tool 204
A Celluloid Protector for Drawings 483
Lacquering Effect on Polished Steel. H. T. Millar 545
Lang, L. F.:
Method of Dividing Fractions by Two 660
Lantern with Colored Slides, Projecting 133
Lathe, A New Forming..... 519
Lathe and Boring Mills, Work Setting Tool for 366
Lathe as a Special Machine, The. J. M. Menegus 417
Lathe Attachments, Two German 86
Lathe Bore Larger or Smaller, To Make 519
Lathe Centers, Lining Up. C. J. Shaw 153
Lathe Centers, Lubricant for. S. C. S. 545
Lathe Centers, Lubricant for. E. C. Noble 373
Lathe Centers, To Line Up. I. W. Antano 267
Lathe Cuts, Diagram for Computing the Time to Take.. 16
Lathe, Cutting a Gear in a. Jas. McCarthy 655
Lathe, Old Foot-power Metal Turning 577
Lathe Pointer, Spring Fastener for. M. H. Ball 153
Lathe Spindle, Special 36
Lathe Stand on the Same Plane, The Importance of Having the Four Feet of a. H. E. Twomley 54
Lathe, To Level Up a. H. H. G. 483
Lathe Tool "Don't," A..... 467
Lathe Tool for Threading a Taper Tap, To Set a..... 239
Lathe Work, Finding the Cost of. C. D. Salisbury..... 484
Lay Off an Angle with Scale and Dividers, To 250
Lay Out any Angle without a Protractor, To. E. Werner 544
Lead from Slipping in the Pencil Holder, Preventing the. S. J. B. 45
Lead Pencil Making 636
Leaks in the Vacuum System of Compound Engines, Detecting 108
Leather and Iron, Cement for. R. M. 323
Leather Belts, Cement for. O. E. Perrigo 424
Leather Covered Pulleys. C. E. Mink 200
Leaves, Combination Drill Jig with Movable. L. J. G.... 626
Lees, E. J.:
Beam Compass Converted into a Hatchet Planimeter 264
Length of Coil Springs, To Increase the Working. Winamac 660
Leonard, W. S.:
Etching Fluid for Steel.... 373
Letter Space Lines, Draftsman's Device for Drawing. F. W. Bach 541
Level Up a Lathe, To. H. H. G. 483
Lever Lock, Novel 471
Lewis, O. T.:
Shell Counterboring Tool .. 151
Soldering 265
To Delay the Setting of Plaster of Paris 268
Dressing Grinding Wheels to Prevent Glazing 372
Lifting Magnets Interfere with Wireless Telegraphy 25
Light Machine Shop, The. E. H. McClintock 55
Limitation of Speed of Sewing Machines Due to Heating of Needle 131
Lindholm, A. C.:
The Evolution of a Cutter to Reduce Tool Making Cost. 601
Lining Connecting Rods. J. V. N. Cheney 416
Lining Up Lathe Centers. C. J. Shaw 153
Liquid Court Plaster. F. H. Jackson 205
Lister Two-Cycle Engine, The. 84
L. J. G.:
Combination Drill Jig with Movable Leaves 656
Loach, W.:
Lathe Rig for Making Interrupted Thread Taps 39
Loading for Knife Edges, Permissible 642
Loads, Calculations Involving the Stopping and Starting of. L. H. Miller 416
Lobdell Air Hoist for Casting Ladle 166
Locating Device for Screw Slotting Attachment. P. Stern 602
Location of the Pitch Circle in Worm Gearing, On the. R. E. Flanders 122
Lock for the Tailstock Spindle, Quick-acting. S. E. Woodbury 654
Locomotive Crane, Erecting a Hundred-Foot Stack with a. 639
Locomotives, Baldwin Locomotive Works' Enormous Production of 93
Logarithmic Tables, Remarkable 526
Loose Pulley, A Combined Clutch and. C. E. Mink .. 98
Loose Pulley Bearing. C. P. Bossert 368
Loose Scale Caused a Boiler Bag, How 350
Low Speed Tools and High Speed Steel 404
L. S. B.:
Reamer for Accuracy and Speed 261
Hints on Hardening..... 322
Lubricant for Lathe Centers. S. C. S. 545
Lubricant for Lathe Centers. E. C. Noble 373
Lubricant for Lathe Centers, Chalk as a. C. P. L..... 544
Lubricant for Pipe Screw Threads. M. E. Canek.... 102
Lubricant for the V's of Large Planers. O. E. Perrigo.... 490
Lubricants for Redrawing Shells. C. F. Emerson.... 205
Lubricating Machinery, Self-.. 204
Lubricating Mixture for Cutting Thread in Tool Steel. E. Kneen 661
Lubricating Mixture for Cutting Tools. H. T. Millar.. 424
Lubrication of Line-Shafting.. 449
Lucas, J. L.:
The Draftsman and His Work 14
An Adjustable Die, An Angle Cut-off Die 151
Making Tin Tubes 602
Gun Metal Finish..... 606
To Plate Porous Work..... 661
Lunch Room at the Rock Island Arsenal. A. D. Knauel 637
Lusitania, The 617
Lynn Reader: A Round Plug in a Hole of the Same Diameter 319

Machine Part, Designing and Building a. H. P. Fairfield 571
Machine Part, Large Number of Steps Required in Making a 584
Machinery and Tools:
1 47
2 104
3 155
4 207
5 269
6 325
7 375
8 426
9 491
10 546
11 608
12 663
Machinery, Automatic 46
Machine Screw Heads, To Prevent the Bruising of..... 532
Machine Screws, Proposed Standards for 520
Machine Shop, Country. R. E. F. 649
Machine Shop, The Light. E. H. McClintock 501
Machine Tool Builders' Convention 140
Machine Tools are Sold, How. 243
Machine Tools, The Advance in the Prices of 534
Machine Tool, The Efficient Working of a 425
Machining Bushes, Method of. S. J. Fisher 152
Machinist, Receipt for Making a First-class. H. E. Wood. 371
Magnetic Clutch, To Overcome Residual Magnetism in a... 557
Magnetized Sheath-Knives Deflect Compass 661
Magnetize Permanent Magnets, To (H. & W. 2)..... 103
Mainspring Kinks. Robt. Grimshaw 489
Manufacturing Buildings of the B. F. Sturtevant Co..... 57
Man Who Sat on the Wrong Side of the Saw 46
Marcellas, V. H.:
Dies for Making Shuttle Springs 368
To Remove Broken Taps from Brass or Copper... 423
Marikle, J. A.:
Construction of a Bridge Model 553
Marine Turbine, History of the 296
Markets, The World's..... 186
Market, Study the..... 5
Markham, E. R.:
Milling Machine Fixtures:
1 117
2 182
3 233
4 294
Punch and Die Work:
1 580
2 630
Marking Negatives, Method of. 46
Marking Paint. F. Emerson.. 102
Marking Polished Steel. A. Munch 323
Maydole (David) Hammer Co.'s Policy of Replacing Defective Hammers 253
Mayhew, Robt.:
Setting up an Engine Lathe 198
Copper Chucking Strips for Lathe Chucks 417
McAnic:
Mechanical Advertising..... 150
McCarthy, Jas.:
Cutting a Gear in a Lathe. 655
McClintock, E. H.:
The Light Machine Shop... 501
M. E. Canek:
Lubricant for Pipe Screw Threads 102
Cement for Attaching Soft Rubber to Iron or Other Metals 205
To Loosen Pasted Paper... 544
Bicycle Tire Anti-Leak.... 661
McElhany, C. M.:
Changing Gear Ratios..... 371
McGahey, C. R.:
Dimensions of Equal Section and Eccentric Piston Rings 319
Meade, Norman G.:
Tests for Faults in Armatures 478
Measurement, Recent Advances in Fine..... 388
Mechanical Advertising. McAnic 150
Mechanical Drawing, The Teaching of. E. H. Fish.. 384
Mechanical History of the Merrimac Valley, Early. R. E. F. 176
Mechanic of Resource, A. Steel. 261
Mechanics and Engineers, Representative American:
Amos Whitney..... 227
Baxter D. Whitney..... 299
John Richards 349
Christopher M. Spencer... 401
John E. Sweet..... 477
W. R. Eckart..... 511
Dwight Slate 577
Samuel Webber 651
Mechanic Sit While Working, Should a? 461
Melville, David:
Iron Cement 102
Chemicals for Blueprints... 102
Menegus, J. M.:
The Lathe as a Special Machine 417
To Detect a Sound in a Noisy Shop 488
Threading Composition Stems 488
Soldering Alloys..... 545
To Case Harden Cast Iron 606
Cement for Belts..... 606
To Write on Celluloid..... 661
Iron or Steel 661
Mercury, To Remove Grease or Dirt From. H. C..... 606
Merrimac Valley, Early Mechanical History of the. R. E. F. 176
Metal in Punching of Thick Boiler Plate Less Than the Volume of the Hole Made. 469
Metallic Baths, Tempering by Means of 642
Metal Moulds, Casting in.... 30
Metal Sections, Extruded.... 650
Metal to Glass, Cement for Attaching. R. M. K..... 661
Metric Tape as a Circumference Rule, Using. Winamac 605
Micrometer for Internal Thread Cutting, Use of. C. Sherman 153
Micrometer, To Measure a Standard V Thread with a. E. Kroff 267
Microphotography 188
Microphotoscope 305
Midvale Case-hardened Armor Plate, Testing 19
Milan Exposition..... 246
Millar, H. T.:
A Pocket Instrument Case. 46
Keeping Cutting Tools Sharp 96
Estimating the Cost of Machine Work 99
Lubricating Mixture for Cutting Tools 424
To Write With Color on a Drawing that is to be Varnished 490
Lacquering Effect on Polished Steel 545
Miller, L. H.:
Calculations Involving the Stopping and Starting of Loads 416
Mill File Pushed Diagonally Across a Shaft in the Lathe 516
Milling Cutter for Clock Gears, Etc. H. J. Bachmann.... 201
Milling Cutters, "A"..... 389
"Milling Cutters," Comment on. A. L. De Leeuw..... 485
Milling Cutters, Hardening (H. & W. 8)..... 206
Milling Machine Collet. E. W. Norton 487
Milling Machine Fixtures. E. R. Markham.
1 117
2 182
3 233
4 294
Milling Machine Vise Square and Parallel with the Spindle, Tool for Setting. O. Westberg 488
Mink, C. E.:
A Combined Clutch and Loose Pulley..... 99
Leather-Covered Pulleys.... 200
A Dangerous Boiler..... 203
The "Short" Coupling.... 261
Mistakes of Newspaper Reporters 204
Moduli of Circular Sections, Table of. O. E. Thaleg... 150
Moisture in Cylinder of Gas Engine Causes Refusal to Start 463
Monahan, G. F.:
Weighted T-Square Head... 660

Monrad, A. L.:
To Clean Rusted Steel, To Preserve Steel from Rust 323
To Prepare Emery for Lapping Gages 372
Soldering Solution for Steel that will not Rust the Work 373
Builders' Chalk for Scraping and Fitting 423
To Temper Small Coil Springs 424
To Finish Wooden Handles, Gun Stocks, Etc 490
Rust Preventives 541
Glues which Resist Moisture 545
Copper Plating Cast Iron 606
Moody, W. I.:
Ink Bottle Holder 541
Moore Electrical Co.'s System of Lighting Rooms 456
Moore, Stanley H.:
Claying Mixture for Forges 373
Morrison, C. W.:
White Writing Fluids for Blue Prints 323
Moss, Sanford A.:
Systematic Method of Computing Centrifugal Stresses 7
Beam Formulas 32
Formulas and Constants for Gas Engine Design 287
Motion 111
Motor Cars in Wales 245
Motor Drive in a Projectile Shop 633
Motors for Lathes Mounted on Floor 524
M. S. W.:
Boring Bar Cutters 599
Multiplication and Addition, Casting out the "Nines" to Prove. E. W. Bowen 656
Muncy, L. E.:
"Hurry Up" End Mill 101
Self-Centering Chuck 420
To True Up Oilstones 488
To Fasten Paper Labels to Iron or Steel 545
Cement for Mending Rubber Goods 545
Munch, Arthur:
Shaper Tool for Square and Oblong Holes 153
Marking Polished Steel 323

Name for a Manufacturing Business, An Appropriate 404
Nash, Geo. C.:
For Chapped Hands; Eye Wash 323
National Cash Register Co.'s Combined Eating Hall and Lecture Room 242
National Civic Federation, Welfare Work of the 524
National Electric Co.'s Shops, Spiral Gear Cutting in the 92
Naval Engineers Becoming Scarce 356
Naval Gas Engine. M. Joachimson 578
Naylor's (Mr.) Experience Told at the Fall Meeting of the A. S. M. E. 463
Needed Machine, A 356
Negatives, Method of Marking 46
Newton, Wm.:
Imitation Ground Glass 204
A Simple Welding Flux 544
New York Telephone Co.'s Large Edition of Books 662
Niagara Falls Without Destroying Scenic Beauty, Utilizing 364
Niagara River's Horse Power 52
Nickel Vanadium Steel 25
Niles Boring Mills Used in General Electric Co.'s Shop 452
Nines" to Prove Multiplication and Addition, Casting out the. E. W. Bowen 656
Noble, E. C.:
Lubricant for Lathe Centers 373
To Harden Steel Without Scaling 424
Noiseless Ratchet 94
Norton, E. W.:
Construction of a Deep Hole Drill 93
Novel Hollow Mill, A 484
Milling Machine Collet 487
Acids for Etching 490
To Harden Drills for Cutting Glass 606
Nuts and Bolt Heads, Template for Drawing. Winamac 605

Oberg, Erik.:
Spring Screw Threading Dies 625
Oches, M. J.:
Wire Rope Grease, Grease for Gear Wheels 606
O'Donnell, T. E.:
Solution for Bluing Brass 606
Offsetting the Center Line of Gasoline Engine Cylinders 357
O. G.:
Preparing Fine Oil for Delicate Machinery 490
Black Varnish for Iron 490
Bronzing Fluid for Steel 545
Oil for Delicate Machinery, Preparing Fine. O. G. 490
Oil Furnaces 85
Oiling Device for Armature Bearings on Vertical Motors, Automatic 145
Oiling, Drop by Drop System of 470
Oil or Other Thick Viscous Fluid, A New Method of Pumping Heavy Crude Fuel 590
Oil Pumping Process, New 306
Oil Separator 27
Oil Squirt Guns, Air Pumps, Etc., made without Leather Packing 535
Oilstones, To True Up. L. E. Muncy 488
Oil Well Casing, Standard Taper of Thread for (H. & W. 18) 607
Old Kinks, Technical Papers' Repetition of 396
Old Man Gets a Joke on Us, The 596
Origin of Sayings 119
Otis, R. B.:
Blue Printing Formula 102
Oxy-Acetylene Blowpipe, The 469

Pacific Coast Railway Club, Suspension of Business of 642
Packing for Gas Engine Cylinders and Pipe Carrying Gasoline Vapor. H. J. Bachmann 154
Packing for Gasoline Pumps, AA 268
Packing for Ocean Freight, Necessity of Substantial 626
Packing of Machine Tools for Shipment, The. T. S. Bentley 118
Page, J. D.:
Practical Formula for Sensitizing Blue Print Paper 373
Paint Adhere to Galvanized Iron, To Make 585
Paint for Fitting and Scraping. F. W. B. 102
Paint, Marking. F. Emerson 102
Paint Rendered Hard by Baking 439
Paints Which Withstand High Temperatures 108a
Pantograph (H. & W. 10) 324
Paper Labels to Iron or Steel, To Fasten. L. E. Muncy 545
Paper-Making Machine, Large 187
Paper Scales. F. B. Kleinhans 392
Parson Turbine, Setting of the Multiplicity of Blades in the 81
Pasted Paper, To Loosen. M. E. Canek 544
Patching Drawings, Drafting Room Practice. W. G. 238
Patching Tires, A Reminder of the Days of the Wrought Iron Locomotive Tire. W. de Sanno 421
Patent, Chinese Government's First 25
Patent Protection 415
Patent, Seldon 80
Patents, Foreign 68
Patents in Japan 134
Patents in Their Relation to the Gas Engine and the Automobile. S. M. Howell.
1 241
2 333
3 441
Pattern Letters and Figures, Alloy for. O. E. Perrigo 373
Pattern-Making in Washington 249
Pattern Storage System, Novel 37
Pavlik, Jr., F.:
How to Set a Plain Die in a Punch 101
Drilling Compound 102
To Remove Hard Grease Paint, Etc., from Machinery 373
To Make Iron or Steel Rust Proof 423
To Remove Steel Chips from Jigs and the Like 545
Pearce, Geo. P.:
A Warning 96
Pen, Border Line. A. P. Sharp 598
Pencil Holder, Preventing the Lead from Slipping in the. S. J. B. 45
Pendulating Electric Drill, A. Dr. Alfred Gradenwitz 20
Pening, Riveting, Calking and Battering 72
Pennsylvania Railroad, Contract for Construction of Terminal of 566
Pennsylvania R. R. Co.'s Large Order 152
Pennsylvania Railroad System Locomotive Tests 411
Pennsylvania R. R. Motive Power Engineering Association, Organization of 543
Perkins, F. C.:
New Liverpool Auto Fire Engine with Liquid Fuel System 181
Permutator 349
Perplexed:
Plug and Ring Gage, Dry vs. Lubricated 148
Perrigo, O. E.:
To Fasten Rubber to Wood 323
Alloy for Pattern Letters and Figures 373
To Clarify Shellac Varnish 373
Simple Mechanical Devices for Reducing the Cost of Labor on Machine Work 397
Belt Dressing 424
Cement for Leather Belts 424
Lubricant for the Vs of Large Planers 490
To Cement Emery Cloth to Polishing Disk 545
To Improve the Color of Shellac Varnish 606
Perry, R. P.:
To Produce Brown Finish on Steel 545
Peters, Ulrich.:
Design of the Weston Load Brake 558
Photographic Reproduction of Blueprints 525
Picking Up Small Articles with Tweezers. Robt. Grimshaw 604
Pickling Castings 648
Pieces in One Pound When the Weight of a Hundred Pieces is Given, Table Showing Number of 224
Pinion, Fixture for Splining Keyway in Taper Hole of. I. N. Quire 654
Pins, Hardening Transmission Chain. Bristol 599
Pipe Bends 474
Pipe Carrying Gasoline Vapor, Packing for. H. J. Bachmann 154
Pipe Screw Threads, Lubricant for. M. E. Canek 102
Pipe Welding 338
Pistol, The Manufacture of Colt's Automatic Army 457
Piston Engine, A Heated. C. R. King 381
Piston Packing 559
Piston Rings, Dimensions of Equal Sections and Eccentric. C. R. McGahey 319
Piston Rings, New Method of Finishing 413
Pitch Angle of Bevel Gears, Method of Finding. O. Eckelt 419
Pitch Circle in Worm Gearing, On the Location of the. R. E. Flanders 122
Plain Die in a Punch, How to Set. F. Pavlik, Jr. 101
Planer, Clamp 306
Planer, Gleason Generating Bevel Gear 594
Planers, High Speed. Geo. J. Burns 34
Planer, Traveling Head 36
Planimeter, The Hatchet 28
Planing Machine, Turbine 180
Plaster of Paris, To Delay the Setting of. O. L. Lewis 268
Plaster of Paris, to Set Slowly, How to Cause 25
Plaster, Waterproof Paint for. F. L. Engel 323
Plate Porous Work, To. J. L. Lucas 661
Platinum Dishes, Gold Should Not be Used in Repairing 305
Platinum Wire, Invisible 193
Plug and Ring Gage, Dry vs. Lubricated. Perplexed 148
Plug Cocks Tight, Mixture for Making. L. S. Burbank 205
Polishing Unfinished Surfaces. R. A. Lachmann 45
Polishing Wheel on Brass, Running a 518
Polish Wood Handles, To. W. H. Sargent 322
Porous Work, To Plate. J. L. Lucas 661
Portable Hand Shaper or Planing Machine 358
Porter, Geo. G.:
Bevel Gear Chart 18
Power Development of Adirondack Region 405
Power Hack Saw Can Do, What the 651
Power Hammer for Blacksmith Shop, Best Type of (H. & W. 15) 425
Power of Running Water to Move Large Blocks of Stone 305
Power of Victoria Falls 205
Power Plant Design, Effect of Turbine on 357
Power Plant Economics 361
Power Saving in Machine Shops 82
Power Transmission Chart. R. N. Dull 60
Pratt Institute, The Machine Shops of 393
Pratt, J. A.:
To Repair a Feed or Other Water Pipe Temporarily 101
Attaching Cloth to Iron 102
Alloy for Caliper and Gage Rod Castings 424
Smooth Scraping on Steel 489
Speed of Buffing Wheels and Grindstones 541
Determination of Proper Amount of Salt in Hardening Bath 544
Salt Bath for Heating 544
To Prevent Exposed Iron Rusting 545
Preserving Wood 187
Press, A. P.:
How He Cut Off the File 232
Jim and His Drafting Room 266
The Shop and the Home 353
The Bluff That Got Called 535
A Wail from New Jersey 540
Pressed Fits, Allowances for 306
Press Tools for Making a Seamless Cover. W. Van Orman 533
Pressure Required for Stamping United States Coins 103
Pressure Required to Punch a 1-Inch Hole Through a 1-2-Inch Steel Plate 374
Press Work, Some Progress in Simple. H. J. Bachmann 569
Prices Ninety Years Ago, High 32
Prices of Machine Tools, The Advance in the 534
Prizes, Award of 304
Prizes Offered by President of the French Republic 469
Production Lists 197
Projectile Shop, Motor Drive in a 633
Projecting Lantern with Colored Slides 133
Proportional Dividers, Table for Setting 94
Proportions of Hand Taps, The A.A 96
Pulley and Gear Arms 6
Pulley Belts, To Prevent the Squeaking of Loose. Winamac 660
Pulley Crowning. G. A. Gauthier 42
Pulleys, Leather-Covered. C. E. Mink 200
Pumping Engine, The Commercial 306
Pumping Heavy Crude Fuel Oil or Other Thick Viscous Fluid, A New Method of 590
Punch and Die, Making a Blanking. H. R. Huber 39
Punch and Die Work. E. R. Markham.
1 580
2 630
Punch, Automatic Slide Forming. C. H. Rowe 147
Punch Hard Rubber, To. L. C. Carr 661
Punches, Superior Efficiency of High-Speed Steel 586

Quebec Cantilever 175

Radius of Circular Arc, To Find (H. & W. 20) 607
Railroad Frogs, Modern Methods in the Manufacture of 504
Rails Exhibited at International Exhibition of Liege 642
Railway Rates in England 134
Railway Traveling, Danger of 25
Rand, J. R.:
A Novel Method of Making Washers 200
Raper, C. V.:
Turret Tools for Drilling Holes in Capstan Head Screws and Nuts 141
Complete Scheme for Turret Lathe Fixture with Special Set of Tools 341
Rapid-Fire Cartridge Shells, Steps and Press Employed in Making 190
Ratchet, Noiseless 94
Ratchet Stop Handle for Milling Machine Vises. H. F. Howard 370
Ratchet Teeth, Drafting Tool for Sketching. Handyman 604
Ratchet Teeth, Tangents, etc., Tool for Laying Out. C. T. Johnson 597
Reamer for Accuracy and Speed. L. S. B. 261
Receipt Column in Machinery, Appreciation of 584
Receipt for Making a First-Class Machinist. H. E. Wood 371
Recessing Tool for Screw Machine. J. S. S. 603
Reddy, B. H.:
The Design of Billet and Bar Passes 451
Redrawing Shells, Lubricants for. C. F. Emerson 205
Reducing Drawings, Method of Enlarging or. Winamac 657
Reducing the Cost of Labor on Machine Work, Simple Mechanical Devices for. O. E. Perrigo 397
R. E. F.:
Early Mechanical History of the Merrimac Valley 176
Country Machine Shop 649
Reference Tables, To Preserve M. Burgess 545
Re-Inking Time-Clock Ribbons. A. D. Knauel 323
Relief of Taps. H. D. 75
Remde, Ed. H.:
White and Red Solution for Writing on Blue Prints 373
Renkin, W. O.:
Horse Power of Detachable Link Driving Chain 202
Repair a Feed or Other Water Pipe Temporarily, To. J. A. Pratt 101

Representative American Mechanics and Engineers.
Amos Whitney 227
Baxter D. Whitney 299
John Richards 349
Christopher M. Spencer 401
John E. Sweet 477
W. R. Eckart 511
Dwight Slate 577
Samuel Webber 651

Re-Rolling Tracing Cloth to Prevent Curling. W. E. M. 371
Reuleaux, Death of Prof. 88
Reversing Lever Problem. F. H. Smith 98
Rice Hamilton:
Fixture for Cutting Spirals on the Plain Milling Machine 41
Richards, John 349
Riggs, Jno. D.:
Filing Up Engine Cranks .. 198
Ring Thread Gages, Case-hardening. E. Kneen 605
Ring Turning and Facing Fixture. Geo. W. Smith, Jr. . 422
Riveted Joint, Design of a. F. H. Smith 387
Riveting in the Turret Lathe. A. D. Knauel 423
R. M.:
Cement for Iron and Marble. 323
Cement for Leather and Iron 323
To Blacken Zinc for Laying Out 323
To Brass Small Articles . 373
Cement for Steam and Water Pipes 573
R. M. K.:
Cement for Attaching Metal to Glass 661
Cleaning Solution for Brass. 661
Rock Crusher Built by Power & Mining Mchy. Co., Large. 585
Rock Island Arsenal, Lunch Room at the. A. D. Knauel 637
Roll Corrugating Device. Robt. Grimshaw 541
Roller Bearings, The Friction of. C. H. Benjamin 62
Rolling Mill' Engine, Ten Thousand Horse Power. C. R. King 217
Ross, Calvin B.:
A Self-Centering Center Punch 201
To Remove Ink Lines from Tracings 420
Template for Drilling Flanges and Flanged Fittings 482
Rounding Automobile Transmission Gear Teeth, Machine for 85
Round Plug in a Hole of the Same Diameter, A. Lynn Reader 319
Round Robin, A Journalistic .. 223
Rowe, C. H.:
Automatic Slide Forming Punch 147
Royal Gorge in Grand Canyon of Arkansas 586
Rubber Goods, A Cement for Mending. L. E. Muncy 545
Rubber to Iron or Other Metals, Cement for Attaching Soft. M. E. Canek 205
Rubber, To Punch Hard. L. C. Carr 661
Rubber, To Turn. M. Burgess 488
Rubber to Wood, To Fasten. O. E. Perrigo 323
Rusting, To Prevent Exposed Iron. Jas. A. Pratt 545
Rusting, To Prevent Tools. C. P. L. 322
Rust Preventative. H. E. Wood 102
Rust Preventative for Tools. F. H. Jackson 205
Rust Preventative. A. L. Monrad 541
Rust-proof, To Make Iron or Steel. F. Pavlik, Jr. 423

Safeguarding of Life in Theatres, The 308
Safety Deposit Vault in the World, The Largest Armor Plate 469
Salisbury, C. D.:
Finding the Cost of Lathe Work 484
Salt Bath for Heating. Jas. A. Pratt 544
Salt in Hardening Bath, Determination of Proper Amount of. J. A. Pratt 544
Sargent, W. H.:
Shellac Cement 268
To Polish Wood Handles .. 322
Saw, Man Who Sat on the Wrong Side of the 46
Saws Without Warping, To Harden and Temper Thin Circular. S. C. Smith 482
Saw Tooth Roof, Modified Form of 525
S. C.:
Etching Fluid 205
Scale Cast Iron, To. R. B. Casey 323
Scale on a Planer, Graduating a. Carroll Ashley 39
Schieren Factory, The Manufacture of Belting at the ... 464
School to Train Textile Salesmen 80
Scott, J. S.:
Backing-off Spring and Button Dies. 543
Scotty:
The Knife Edge Straightedge 487
Scraping in Fitting and Finishing Machine Tools 154
Scraping on Steel, Smooth. J. A. Pratt 489
Scratch Awl, Hardening a. R. A. Lachmann 101
Screw Clamp with Spherical Adjustment 366
Screw Driver with Knock-Out Pin. O. Westberg 489
Screw Slotting Attachment, Locating Device for. P. Stern 602
Screws, Proposed Standards for Machine 520
Screws, To Preserve. C. Ashley 322
Screw Threads, Angles of. T. E. Welsh 521
Screw Trust 187
Screw Was Cut, How a Coarse Pitch. W. L. Fay .. 600
Scroll Cutter for Cutting Scroll Chucks 605
S. C. S.:
Lubricant for Lathe Centers 545
Seamless Cover, Press Tools for Making a. W. Van Orman. 533
Secrecy Some Evils of Extreme 641
Secrecy to Protect a Process, Danger of Relying on 487
Sections of Cast Iron Beams. C. H. Benjamin 437
Selden Patent 80
Self-centering Center Punch, Calvin B. Ross 201
Self-centering Center Punch, A. Clay-Bean 369
Self-centering Chuck. L. E. Muncy 420
Self-lubricating Machinery 204
Selling Machine Tools, The Importance of 240
Sensitizing Blue Print Paper, Practical Formula for. J. D. Page 373
Set a Plain Die in a Punch, How to. F. Pavlik, Jr. 101
Setting Cutters Accurately on the Universal Milling Machine. W. C. Force 320
Setting of the Multiplicity of Blades in the Parson Turbine 81
Setting Proportional Dividers, Table for 94
Setting Up an Engine Lathe. Robt. Mayhew 198
Seventy Years Ago 564
Sewing Machines, Limitation of Speed Due to Heating of Needle 131
Shaft for Babbitting, To Prepare a. V. Smith 423
Shafting, Table for Computing Hollow and Solid 20
Shailor, F. E.:
Hardening Without Cracking 318
Shape of Dies for Threading Steel Pipe 82
Shaper Tool for Square and Oblong Holes. A. Munch .. 153
Sharp, A. P.:
Border Line Pen 598
Sharpening Device, Novel Band Saw 94
Shaw, C. J.:
Lining Up Lathe Centers ... 153
Draw-in Chuck for Engine Lathes 419
Shear Blades, Process of Making (H. & W. 4) 206
Shear Blades, Welding of Steel on Iron Backs of (H. & W. 4) 206
Shee, P. B.:
To Clean Jewelry, Silverware and Metals 545
Shellac Cement. W. H. Sargent 268
Shellac Varnish, To Clarify. O. E. Perrigo 373
Shellac Varnish, To Improve the Color of. O. E. Perrigo 606
Shell Counterboring Tool. O. L. Lewis 151
Shelley, C. W.:
Die Sinkers' Impression Wax 102
Shells, Lubricants for Redrawing. C. F. Emerson 205
Sherman, Chas.:
Use of Micrometer for Internal Thread Cutting 153
Shipment, The Packing of Machine Tools for. T. S. Bentley 118
Shock Absorber 613
Shock Absorber, Edo 653
Shop and the Home, The. A. P. Press 353
Shop Descriptions 186
Shop of the Hoefer Mfg. Co., New 171
Shop Receipt after Undergoing Spelling Reform, "Machinery's" 642
Shops, Visiting. Entropy 76
Shop Training for the Draftsman, The Advantage of Practical 41
Shop Visitors—Rolling in Babbitt—Planer Tool Lifter. H. P. Fairfield 537
"Short" Coupling, The. C. E. Mink 261
Shuttle Springs, Dies for Making. V. H. Marcellus 368
Side of a Square Equal to Area of Given Circle, To Obtain. 249
Silsby, Horace 87
Simple Mechanical Devices for Reducing the Cost of Labor on Machine Work. O. E. Perrigo 397
Sine of an Angle Below 80 Degrees, Formula for Obtaining 81
S. J. B.:
Preventing the Lead from Slipping in the Pencil Holder 45
Skeleton Type, Early Buildings of the. H. A. Coombs 338
Skilled Labor Increased by Instruction 445
Slate, Dwight 577
Sleigh, Motor-driven 543
Slide-forming Punch, Automatic. C. H. Rowe 147
Slip Gear, Improvised. Bessemer 598
Slow, Advantages of Going ... 640
Smith, F. H.:
Reversing Lever Problem ... 98
Design of a Riveted Joint .. 387
Smith, Jr., Geo. W.:
Ring Turning and Facing Fixture 422
Smith, S. C.:
To Harden and Temper Thin Circular Saws without Warping 482
Smith, V.:
To Prepare a Shaft for Babbitting 423
Smoke, Concentrating Power to Reduce 132
Smoke Question, The 191
Snout Boring Machine, The ... 468
Solder, Aluminum. L. C. Carr 661
Solder Brass or Steel to Steel, To. Carroll Ashley 204
Soldering. O. L. Lewis 265
Soldering Alloys. J. M. Menegus 545
Soldering Acid, Improved 193
Soldering Fluid, Non-rusting. J. H. V. 606
Soldering Solution for Steel that will not Rust the Work. A. L. Monrad 373
Solder Small Pieces Together; Notes on Soldering. M. Burgess 489
Solid Lathe Arbors. H. D. .. 462
Sosa, A. M.:
The Geared Drive 367
Sound in a Noisy Shop, To Detect a. J. M. Menegus .. 488
Space Occupied by Turbines and Engines, Relative 22
Speed Box, The Conradson ... 257
Speed Indicator, Ammeter Used as a 8
Speed Lathe, Threading Attachment for the. R. H. Fuerle 199
Spelling Reform, "Machinery's" Shop Receipt after Undergoing 642
Spencer, Christopher M. 401
Spherical Boring Bar. Ward. 597
Spindle Forgings, High Speed Drill for. C. B. 147
Spiral Gear Cutting in the National Electric Co.'s Shops. 92
Spiral Gears, Cutting. E. H. Fish 65
Spirals on the Plain Milling Machine, Fixture for Cutting. Hamilton Rice 41
Splining Keyway in Taper Hole of Pinion, Fixture for. I. N. Quire 654
Spring Fastener for Lathe Pointer. M. H. Ball 153
Spring Indicators, Some German Outside. Dr. Alfred Gradenwitz 72
Spring-Nut for Change Gears .. 613
Spring Screw Threading Dies. E. Oberg 625
Springs, To Increase the Working Length of Coil. Winamac 660
Spur Gearing and Worm Gearing, The Difference Between the Actions of 469
Squeaking of Loose Pulley Belts, To Prevent the. Winamac 660
Stabel, J. M.:
Brightening and Coloring Brass 597
Varnish for Iron Work 661
To Braze Steel and Iron without Heat 661
Stack with a Locomotive Crane, Erecting a Hundred-Foot 639
Stained Bottles, To Clean. Geo. Williamson 322
Staircase Higher to Avoid Congestion, Making Bottom Steps of a 592
Stamps, Poor Centering of U. S. 614
Standard and V-Threads, Depths of U. S. 206
Standard Crown Nuts with Lock 415
Standard Screw Threads—2, Making 476
Standards for Machine Screws, Proposed 520
Standard Units of Weights and Measures, Difficulties in Establishing 305
Start a Threading Die, To. R. A. Lachmann 101
Starting Crank for Gas Engines, Non-Return 248
Steam and Water Pipes, Cement for. R. M. 373
Steam Boilers, Water Gages for 31
Steam Condensers, A Neglected Point in 136
Steam Engine Enhanced, Economy of 603
Steam Engineering Practice, Prejudice in 305
Steam Engines, Valve Operating Mechanism for 27
Steam Fitting, Weak. Gulf .. 486
Steam Gage Pipes, Danger of Cocks in 103
Steam Hammers and the Horse Power Required for Operation, Rules for Finding the Capacity of. L. N. Gillis .. 370
Steam Turbine, Allis-Chalmers 236
Steam Turbine Installations, Large 28
Steam Turbines, Data on the Use and Performance of 161
Steam Turbines, Experiences with 564
Steam Warming and Ventilating in America, Early History of 360
Steel:
A Mechanic of Resource ... 261
Steel, Alloys for Drawing Colors on. M. Dehne 323
Steel and Iron without Heat, To Braze. J. M. Stabel ... 661
Steel, Bronzing Fluid for. "O. G. 545
Steel from Rust, To Preserve. A. L. Monrad 323
Steel? Iron or. J. M. Menegus 661
Steel, Lubricating Mixture for Cutting Thread in Tool. E. Kneen 661
Steel, Marking Polished. A. Munch 323
Steel, Nickel Vanadium 25
Steel on Iron Backs of Shear Blades, Welding of (H. & W. 4) 206
Steel or Iron, To Anneal. R. B. Casey 102
Steel, Strength and Ductility of. F. E. Cardullo 556
Steel, Tempering Compound for. H. G. Kroeger 268
Steel, To Clean Rusted. A. T. Monrad 323
Steel, To Drill Hard. G. E. Hetzler 424
Steel, To Drill Hardened. M. Burgess 488
Steel Tools in their Handles, To Keep. M. E. Howe 545
Steel, To Produce Brown Finish on. R. P. Perry 545
Steel, To Restore Burnt. "A. A." 205
Steel without Scaling, To Harden. E. C. Noble 424
Steel Works, Advance in the Mechanism of 27
Steen, J. C.:
The Geared Drive 195
Sterling, F. G.:
Bluing for Laying out Work 322
Grinding a Combination Flat Drill and Mill 604
Stern, Philip:
Locating Device for Screw Slotting Attachment 602
Steuart, F. R.:
Time Saving in the Drafting Room 655
Some Tracing Methods 656
Sticking Emery Paper on Small Grinder Disks, Cement for. H. J. Bachmann 154
Stoker, Mechanical 585
Stopping and Starting of Loads, Calculations Involving the. L. H. Miller 416
Storage of Explosive Liquids, Safe 189
Stresses Thrown upon Bolts by the Wrench, On the 29
Strike, Individual Responsibility of Members of a Union for Losses to a Concern Caused by 642
Study the Market 5
Sturtevant (B. F.) Co., Drafting Room of the 1
Sturtevant (B. F.) Co.'s Economizers Installed in Power House of Interborough Rapid Transit Co. 423
Sturtevant (B. F.) Co., Manufacturing Buildings of the .. 57
Submarine Elevator for Raising Wrecked Vessels 249

Substitute for Cement on Grinder Disks. G. Huber.. 268
Subway Engines, Interborough Rapid Transit Co., Test of 348
Sulphur Bed in Calcasieu Parish, La. 26
Sulphur Exporting in New Orleans 133
Superheated Steam Problem... 81
Surveying without Instruments. A. L. DeLeeuw 565
Sweet, John E. 477
Sweet, S. H.:
Bright Dip for Brass, Copper and Bronze 154
Syndication of Contributions.. 641
Systematic Method of Computing Centrifugal Stresses. S. A. Moss 7

Table for Computing Hollow and Solid Shafting 20
Table for Setting Proportional Dividers 94
Table of Moduli of Circular Sections. O. E. Thaleg.. 150
Table Showing Number of Pieces in One Pound, When the Weight of a Hundred Pieces is Given 224
Tail-Rods, The Value of..... 95
Tailstock Spindle, Quick-Acting Lock for the. S. E. Woodbury 654
Tangent Circles, To Find the Diameter and Location of a Roll which will Touch Three 374
Tangent Circles (H. & W. 16) 425
Tantalum 566
Tantalum 119
Tantalum for Tool Making... 239
Tantalum Pens 525
Taper Tap, To Set a Lathe Tool for Threading a..... 239
Taper of Thread for Oil Well Casing, Standard (H. & W. 18) 607
Tap Hole for 14-24 Tap, Proper Size to Drill (H. & W. 21) 662
Taps and Chucking Reamers, Thickness of Cutters for. J. A. P. 543
Taps from Brass or Copper, To Remove Broken. V. H. Marcellus 423
Taps, Lathe Rig for Making Interrupted Thread. W. Loach 39
Taps, Relief of. H. D..... 75
Taps, To Remove Broken. H. J. Bachmann 267
Tariff, Japanese 648
Tariff Regulations 356
Taylor, Frederick W..... 255
Taylor System of Shop Management, A Discussion of the 414
Teaching of Mechanical Drawing, The. E. H. Fish..... 384
Technical Education, Some Expert Opinions on 250
Technical Reading and Formulas. C. F. Blake:
1. General Remarks on Self-Education 69
2. Strains and Strength of Materials 125
3. Graphics 178
Technolexicon of Society of German Engineers, Report of 642
Temper a Twist Drill to Drill Hardened Steel, To. H. J. Bachmann 322
Tempering by Means of Metallic Baths 642
Tempering Compound for Steel. H. G. Kroeger 268
Tempering of Copper..... 44
Template for Drawing Nuts and Bolt Heads. Winamac..... 605
Template for Drilling Flanges and Flanged Fittings. C. B. Ross 482
Template for Stamping with Steel Letters. F. Hillix.... 372
Ten Thousand Horse Power Rolling Mill Engine. C. R. King 217
Testing Air Brakes, Device for 95
Testing the Flow of an Artesian Well 187
Tests for Faults in Armatures. N. G. Meade 478
Tests of Belt Preparations.... 364
Texas:
Closing a Keyseat in Nickel Steel Shafts 148
Boring Bar for Boring Taper Holes 321
Textile Salesmen, School to Train 80
Thaleg, O. E.:
Tables of Moduli of Circular Sections 150
Theatres, The Safeguarding of Life in 308
Thermit Repair Job made by Goldschmidt Thermit Co. .. 586
Thick Cylinders. J. S. Holliday 13
Thickness and Width of Driving Belt Determined by Factor of Safety 187
Thiel, C. P.:
A Drawing Room Instrument Holder 44
A Hollow Mill and Jig.... 263
Third Rail, Poor Construction 258
Thread Cleaners for Chucks and Faceplates. H. J. Bachmann 267
Thread Cutting, Use of Micrometer for Internal. C. Sherman 153
Threading Attachment for the Speed Lathe. R. H. Fuerle 199
Threading Composition Stems. J. M. Menegus 488
Threading Die, To Start a. R. A. Lachmann 101
Threading Oversize Bolts with Hand Dies. R. W. Harris. 605
Threading Steel Pipe, Shape of Dies for 82
Threading Tool, Combination. E. Kneen 659
Threading Tool Holder for High Speed Steel. S. Courter 660
Threads, Triangle for Drawing. J. W. Coleman..... 655
Thread Tools, Making Accurate 365
Thumb Tack Puller, Ink Eraser and. E. C. Falk 605
Tidal Power 82
Tight-Screwed Joints, Making. 251
Time Clock Checking System Employed in Sibley College. 476
Time Clock Ribbons, Re-inking. A. D. Knauel 323
Time Saving in the Drafting Room. F. R. Steuart 655
Time Switch for Lighting Offices, Drawing Rooms and Shops 357
Time to Take Lathe Cuts, Diagrams for Computing the.. 16
Tin Consumed Annually in U. S. 633
Tin for Laying Out, To Blacken. F. W. Bach 490
Tin, To Coat Brass or Copper with. H. C. 490
Tin Tubes, Making. J. L. Lucas 602
Titles and Border Lines on Drawings 40
T. J.:
A Broaching Die 659
Todd, W. J.:
The Manipulation of High Speed Steels 313
Tool Holder for High Speed Steel, Threading. S. Courter 660
Tool Holder and a Die Maker's Square, Two. C. Ashley.. 43
Toolmaker:
Hardening Formula for Cutting Tools 606
Tool Maker and Mechanical Engineer, The 640
Tool Makers' Vise. O. Westberg 485
Tool Steel, To Successfully Cold-water Anneal. C. F. Emerson 101
Toothed Clutch. A. Gottschalk 600
Torsional Strength of Steel and Wrought Iron, Relative. 405
Touching Circles, The Problem of. A. L. De Leeuw..... 444
Toughen and Surface Harden Cast Iron, To. J. H. V... 545
Towne (T. T.), Death of.... 374
Tracing Cloth to Prevent Curling, Re-rolling. W. E. M. 371
Tracing Methods, Some. F. R. Steuart 656
Tracing, To Clean a. R. F. Kiefer 369
Trade Journalism, Emerson P. Harris on 466
Trademarks, Distinctive 468
Trade of Hamburg, Immense. 642
Trade Paper, The Growth of the 639
Transformer Having Thin Corrugated Shells Built by the General Electric Co. 585
Transmission Chain Pins, Hardening. Bristol 599
Transparent, To Make Van Dyke Prints. E. W. Bowen 661
"Traveler":
Gas Engineering in the Orient 235
Traveling Head Planer 36
Traverse Screw, Cutting a.... 95
Triangle for Drawing I-Beam Sections. Roger De L. French 96
Triangle for Drawing Threads. J. W. Coleman 655
Truesdale Coal Breaker of the Lackawanna Coal Co. 398
True Up Work in the Lathe, To. M. Watrous 544
T-Square Head, Weighted. G. F. Monahan 660
Tubes, An Unusual Method of Making. C. D. King..... 42
Turbine Blades 245
Turbine-driven Cunard Liner, The 311
Turbine, Experiences with an Allis-Chalmers 593
Turbine Fallacies, Some 472
Turbine, Gas or Oil for Driving 188
Turbine has Succeeded, Why the 80
Turbine on Power Plant Design, Effect of 357
Turbine Planing Machine 180
Turbines and Engines, Relative Space Occupied by..... 22
Turbines, Willans-Parsons.... 337
Turbine Troubles 505
Turbo-Generating Set, Crocker-Wheeler-Terry 35
Turnbull, D. C.:
An Ink Bottle Holder..... 45
Turning Locomotive Tires, Rule for Approximating Time Required for 545
Turntable, Automobile 95
Turpentine for Wounds, Use of. F. H. Jackson 205
Turret Knurling Tool. C. C. Arras 605
Turret Lathe Fixture with Special Set of Tools, Combined Scheme for. C. V. Raper 341
Turret Tools for Drilling Holes in Capstan Head Screws and Nuts. C. V. Raper..... 141
Turret Work, Automatic. P. W. Abbott 421
Twist Drill, Extemporized Driver for, C. F. Emerson. 604
Twist Drill to Drill Hardened Steel, To Temper a. H. J. Bachmann 322
Twomley, H. E.:
To Bind Data Sheet No. 48 374
The Importance of Having the Four Feet of a Lathe Stand on the Same Plane 540
Two Point Ball Bearings, Designing 384

Unfinished Surfaces, Polishing. R. A. Lachmann 45
Union for Losses to a Concern Caused by a Strike, Individual Responsibility of Members of a 642
United States Coins, Pressure Required for Stamping 103
Unloading Coal Cars 64
Unskilled Labor, What is.... 132
Untaxed Denaturized Alcohol.. 471

Value of Exponent n in Expression $PV^n = Constant$ 405
Value of the Expression $x^2 + x + 41$ 445
Valve for Unobstructed Flow of Liquid, Check 95
Valve Gear Embodying a Novel Mechanical Movement, A New 114
Valve Operating Mechanism for Steam Engines 27
Vandyke Prints Transparent, To Make. E. W. Bowen.. 661
Van Orman, W.:
Can Bottom Punch and Die. 466
Press Tools for Making a Seamless Cover 533
Van Yorx, Jr., J. H.:
Estimating Time on Machine Work 289
Variable Speed Mechanisms:
5. Ratchet Devices 53
6. Geared Devices 167
7. Geared Devices (Cont.).. 246
8. Geared Devices (Cont.).. 339
9. 449
Varnish for Iron Work. J. M. Stabel 661
Velocity Ratio Due to Belt Elasticity, Loss of 250
Ventilation of the New York Subway 624
Vestibule for the Shipping Room, Pullman 613
Victoria Falls 91
Victoria Falls, Power of..... 205
Vise, Toolmakers'. O. Westberg 485
Visiting Shops. Entropy 76
Voltage Required to Run ¼ H.P. Motor (H. & W. 7).. 206
Volumetric Capacity of Fans.. 26
Voris, O. E.:
Glycerine-Litharge Cement.. 661
V's of Large Planers, Lubricant for the. O. E. Perrigo 490
V-Threads, Depths of U. S. Standard and 206
V-Thread with a Micrometer, To Measure a Standard. E. Kroff 267

Wackermann, F.:
Horse Power Transmitted by Belts 559
Cutters of Cold-Rolled Steel. 602
Wagenhorst & Co.'s (J. H.) Electric Blue Printing Machines, Prices of 366
Wail from New Jersey. A. P. Press 540
Ward:
Spherical Boring Bar..... 597
Warner (James C.), Death of. 305
Warning, A. Geo. R. Pearce.. 96
Warping in Hardening, To Prevent Blanking Dies from Excessive. C. F. Emerson 204
Warping of Celluloid Protractors (H. & W. 5) 206
Warrant Machinists in the Navy, The 107
Washers, A Novel Method of Making. J. R. Rand 200
Washing Machine 153
Waste Product, A 268
Watch Dials, Process of Making 332A
Watchman's Application for a Job, A Would-be 467
Water and Oil Proof Cement. Albert Elmiger 205
Water, Effect of Rapid Changes in the Velocity of..... 358
Water Gages for Steam Boilers 31
Water Hoist, A Novel..... 169
Water Jackets, To Repair Frost-Cracked. W. D. Graves 322
Water Power in the Alps.... 188
Waterproof Cement 596
Waterproof Cements for Glass. A. L. Graffam 424
Waterproof Paint for Plaster. F. L. Engel 323
Watervliet Arsenal Exhibit... 340
Watrous, M.:
To True Up Work in the Lathe 544
Waves of the Sea Have Little Progressive Motion 396
Wear of Modern Guns, Rapid. 357
Webber, Samuel 651
Weber, H. M.:
For Coloring Brass Blue Black 661
Weighted T-Square Head. G. F. Monahan 660
Weiss Exhaust Muffler for Gas Engines 479
Welding Flux, Simple. Wm. Newton 544
Welding of Steel on Iron Backs of Shear Blades (H. & W. 4) 206
Welding of Track Joints, Local 624
Welfare Work of the National Civic Federation 524
Welsh, T. E.:
Angles of Screw Threads.. 321
W. E. M.:
Re-Rolling Tracing Cloth to Prevent Curling 371
Werner, E.:
To Lay Out Any Angle without a Protractor 544
Westberg, O.:
Toolmakers' Vise 485
Tool for Setting Milling Machine Vise Square and Parallel with the Spindle. 488
Screw Driver with Knock-out Pin 489
Parallel Vernier Gage 601
Westcott, A. L.:
To Calculate the Center Angles of a Pair of Bevel Gears Having Their Axes at Other Than Right Angles 539
Western Electric Co., New Shops of the 560
Westinghouse, Church, Kerr & Co., Purchased by Kean Van Cortlandt & Co. 523
Weston Electrical Instrument Co.'s Shop, Social Features of the 196
Weston Load Brake, Design of the. U. Peters 558
W. G.:
Drafting Room Practice, Patching Drawings 238
W. H. A.:
Making Blue Prints from Typewritten Originals... 264
Wheeler, E. S.:
Some Annealing Methods... 600
Wheel Press, Increase in Size and Power of the 585
White, G. E.:
A Cutter Holder for Slotter 203
An Inserted Tooth Cutter.. 267
White Mice as Detectors of Gasoline Leaks 206
White Writing Fluid for Blue Prints. C. W. Morrison... 323
Whiting Surfaces for Laying Out Work. A. D. Knauel.. 424
Whitney, Amos 227
Whitney, Baxter D. 299
Wilford, J. W.:
To Make a Simple Casting from a Broken One 488
Iron Cement 490
Willians-Parsons Turbines..... 337
Williamson, Geo.:
To Clean Stained Bottles.. 322
Winamac:
Template for Drawing Nuts and Bolt Heads 605
Using a Metric Tape as a Circumference Rule 605
Method of Enlarging or Reducing Drawings 657
To Increase the Working Length of Coil Springs.. 660
To Prevent the Squeaking of Loose Pulley Belts 660
Wind as a Motive Power, Use of 26
Winding of Direct Current Armatures 345
Windmill Tower, Safest Place for 25
Wire Due to Electrolysis, Lack of Endurance of..... 291
Wireless Telegraph 159
Wireless Telegraphy, Lifting Magnets Interfere with 25
Wire Rope Grease. M. J. Oches 606

Wolseley Tool & Motor Car Co.'s Six-Cylinder Gasoline Engine to be Used by the Delaware & Hudson Co.... 358
Woodbury, S. E.:
A Quick-Acting Lock for the Tailstock Spindle 654
Wood Craft 132
Wood (E. E.) Accepts Position as General Manager of Geo. D. Walcott & Son..... 425
Wooden Handles, Gun Stocks, etc., To Finish. A. L. Monrad 490
Wood Handles, To Polish. W. H. Sargent 322
Wood, H. E.:
Hard Lines for Draftsmen. 73
Rust Preventative 102
Practical Don'ts for Machinists—II 231
Receipt for Making a First-class Machinist 371
Wood, Preserving 187
Wood to Tin Plate, Fastening. 321
Woodworth, J. V.:
A Set of Accurate Test and Inspection Gages for Small Duplicate Work.... 73
Work Setting Tool for Lathe and Boring Mills 366
Worm Drive, The "Globoid." Robt. Grimshaw 177
Worm Gearing, On the Location of the Pitch Circle in.. 122
Worm Gear, The. John Edgar 63
Worm Wheel, Split. G. E. H. 597
Wrist Pins and Tumbling Shafts, Tool for Turning.. 366
Write on Celluloid, To. J. M. Menegus 661
Write with Color on a Drawing that is to be Varnished, To. H. L. Millar 490
Writing Solution for Blue Prints, Red and White (H. & W. 3)..... 206
Wrought Iron Pipes, Manufacture of 228
W. T. M.:
Grinding Eight-Inch Finishing Rolls 152
W. W. W.:
Mounting Blue Prints 486

Zinc Casting for Ornamental Work 136
Zinc for Laying Out, To Blacken. R. M..... 323
Zinc, To Blacken 324

لم